

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3341-42)

Set a post 3½ ft. long, 3" sq., 24" in the ground, for ¼ sec. cor. marked ¼ S on N. face, from which
A Fir 48" dia., bears N.54°E., 60 lks. dist. mkd. ¼ S BT.
A Fir 48" dia., bears S.38°E., 28 lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - May 14, 1958 - C.S. File 49/88-4

Found both orig. BTs and each has good scribing and each is down, (windblown).

Set Brass cap at cor. mkd: County Surveyors Office
T 24 S R 8 W
¼ S 27
S 34
1958

New BTs- 5" R.Fir bears N.49½°E., 25.4 ft. scribed ¼ S27 CS BT.
14" R.Fir bears S.50°E., 11.6 ft. scribed ¼ S34 CS BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Jan/Feb. 1967 - C.S. File 54/12-1

Found - 1958 DCSO brass cap. Brass cap is bent over under 24" Fir log.

5" D.Fir, down and burned, N.49½°E., 25.4 ft., shows "¼ S27 CS" on unhealed and burned blaze.

14" D.Fir, down and nearly buried, S.50°E., 11.6 ft.
New BTs- 7" D.Fir N.41°E., 60.6 ft. mkd. ¼ S27 CS BT.

10" D.Fir S.2½°E., 151.0 ft. mkd. ¼ S34 CS BT.
Corner lies on steep E. slope, approx. 100 ft. S. of E-W timber line in logged and burned area.