

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCS0 records Vol. 8 Page(s) 3336)

Set a post 3½ ft. long, 3" sq., 24" in the ground, for ¼ sec. cor. marked ¼ S on W. face, from which
A Fir 20" dia., bears S.38°W, 29 lks. dist. mkd. ¼ S BT.
A Fir 18" dia., bears N.4°E., 28 lks. dist. mkd. ¼ S BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
April 25 1966 - C.S. File 49/84-19

Found - Orig. 18" now 27" Fir N.4°E., 18.5 ft., open and shows "¼" scribe. This BT now down and dead.
Orig. 20" now 36" Fir, down and dead, S.38°W., 19.1 ft., shows good scar. We do not open.
DO NOT SET BRASS CAP AT THIS TIME, because of proposed road construction.
New BTs- 9" W.Fir N.47°E., 30.2 ft. mkd. ¼ S11 CS BT.
18" D.Fir N.49°W., 26.3 ft. mkd. ¼ S10 CS BT.
8" D.Fir N.11°W., 61.7 ft. mkd. ¼ S10 CS BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Oct. 19, 1966 - C.S. File 49/84-23

(Found three BTs mkd. in previous visit)
RESET brass cap removed for road construction from BTs.
Corner lies approx. 40 ft. West of approx. center line of new access road and 20 ft. West of top of cut bank. Road, course NE.

Fd. OK, May 1969 by DCS0, V. Tracy - C.S. File 54/55-5