

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 540100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 35; & Sec. 2, T25-8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 292, dated Aug. 7, 1878 - (DCSO records Vol. 8 Page(s) 3294)

-----  
Set a Fir post 4 ft. long, 5" sq., 18" in ground for the qr. sec. cor., from which  
A Fir 14" dia., bears S.45°E., 26 lks. dist.  
A Fir 24" dia., bears N.8°W., 28 lks. dist.

Fd. corner in good condition in GLO Survey by - A. R. and S.C.Flint, Under Contract #392, dated May 26, 1881 (DCSO records Vol. 8 Page(s) 3302)

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; S. Bilow, crew - May 14, 1958 - C.S. File 49/88

-----  
Found both orig. BTs, both check for bearing and distance.  
Orig. 24" now 36" R.Fir N.8°W., 18.5 ft., good bark scribe "1/4 S".  
Do not find scribing on SE. BT, center rotted.  
Set Brass cap at cor. mkd: County Surveyors Office  
1/4 S 35 T24S R8W  
S 2 T25S R8W  
1958  
New BTs- 20" Cedar bears S.70°W., 38.0 ft. scribed 1/4 S2 CS BT  
36" R.Fir bears N.8°W., 18.5 ft. bark scribed 1/4 S35 CS BT.

Douglas Co. Surveyors Office - Bruce R. Rogers, Deputy - Crew, Mike Stone - April 1965 - C.S. File 49/84-15

-----  
Found - 1958 DCSO brass cap at corner.  
20" Cedar, now snag, S.70°W., 38.0 ft. scribing visible.  
36" R.Fir, down, N.8°W., 18.5 ft. bark scribing visible.  
New BTs- 5" W.Fir S.86°W., 45.0 ft. mkd. 1/4 S2 CS BT.  
8" Cedar N.31°E., 53.0 ft. mkd. 1/4 S35 CS BT.

BLM Resurvey by Dale T. Bedell, Cadastral Surveyor, under Group #1241, Surveyed April/May 1986 - (DCSO records Vol. 47 Page(s) 18119)

-----  
The 1/4 sec. cor. perpetuated and recorded by Byron in 1958, monumented with an iron post 1 1/2" dia., firmly set, projecting 15" above ground with brass cap mkd. in 1958 from which the remains of the original bearing trees:  
(Cont. Next Page)

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 540100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 35; & Sec. 2, T25-8

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

A Fir snag 12" dia., bears S.45°E., 26 lks. dist., no marks visible on an opened blaze.  
A Fir stump 30" dia., bears N.8°W., 28 lks. dist., bark scribed marks 3 B visible.  
and the remains of a bearing tree mkd. by Byron:  
A Cedar stump 25" dia., bears S.70°W., 58 lks. dist., with scribe marks BT visible on partially healed blaze.  
and a bearing tree mkd. by Rogers in 1965:  
A Cedar 13" dia., bears N.31°E., 81½ lks. dist., with a healed blaze.  
and a new bearing tree:  
A Fir 18" dia., bears S.12°W., 18 lks. dist., mkd. ¼ S2 BT Corner is on level, swampy ground.

Bruce Shaner - Dec. 7, 2000 - C. S. File 65/33-20  
-----  
Found - 2½" brass cap, properly marked, on a 1" iron pipe, from which a:  
25" Cedar BT, now stump, bears S.70°W., 38.3 ft. (scribes not visible)  
18" Cedar BT, face overgrown, bears N.31°E. 53.8 ft.  
24" D.Fir BT, (rec. 18") bears S.12°W., 11.9 ft., face overgrown.  
Other BTs now gone.  
Set - 2 each 6 ft. steel fence posts:  
1 at south, 1.0 ft.  
1 at west, 1.0 ft.  
Note - Corner is north a distance of 100 ft. from E-W logging spur road.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 3/18/26 - C.S. File 67/62-25  
-----  
Found - 2½" DCSO brass cap on iron pipe.  
County Surveyors Office  
¼ S 35 T24S R8W  
S 2 T25S R8W  
1958  
25" x 1 ft. rotted sawn cedar stump S.70°W. 38.3 ft.  
21" cedar N.31°E. 53.8 ft. healed face.  
29" down D. Fir (Rec. S.12°W. 11.9 ft.)  
2 - steel fence posts  
South 1.0 ft.  
West 1.6 ft.  
UNRECORDED - 6" D.Fir, north 11.0 ft Unmarked, has R.R. tag  
Compass decl. 14¼°E.  
TRIMBLE GEO XT POSITION  
43°.43252703 N. 123°.61424566 W.