

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 12

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3323)

-----  
Set a post 3½ ft. long, 3" sq., 24" in the ground for ¼ sec. cor. marked ¼ S on W. face, from which  
A Cedar 10" dia., bears S.80°E., 90 lks. dist. mkd. ¼ S BT  
A Fir 12" dia., bears N.5°W., 52 lks. dist. mkd. ¼ S BT.

BLM corner remonumentation by Harold D. Corbin, Cadastral Surveyor, under Group #'s 350 and 427, Surveyed June 1959 - (DCSO records Vol. 30 Page(s) 12612)

-----  
The ¼ sec. cor., determined at record bearing and distance from the only remaining original bearing tree:  
A Cedar 28" dia., bears S.80°E., 90 lks. dist. with scribe marks ¼ visible on partially opened blaze.

At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 26" in the ground, with brass cap mkd:  
T 24 S R 8 W  
¼  
S 11|S 12  
1959

from which  
A W.Fir 7" dia., bears N.14¾°E., 73 lks. mkd. ¼ S12 BT.  
A W.Fir 6" dia., bears S.71°W., 89 lks. mkd. ¼ S11 BT.

Mark Smalley, Roseburg Forest Products - Party Chief: Willam Olson - 6/2009 - C.S. File 65/66-24

-----  
Condition report only  
Found - 1959 BLM brass cap  
23" Fir S.35°E., 27.3' healed face 1996 unrecorded RFP renewal  
19" Fir S.78°E., 14.6' healed face 1996 unrecorded RFP renewal  
9" Fir S.32°W., 36.5' healed face 1996 unrecorded RFP renewal  
18" Fir N.63°E., 31.2' healed face 1996 unrecorded RFP renewal  
Note - Compass decl. 18°E.