

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5 & 6; 31 & 32, T23-9

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 292, dated Aug. 7, 1878 - (DCSO records Vol. 6 Page(s) 2627)

-
- Set Fir post 40" long, 5" dia., 18" in ground for the corner to sec. 5 and 6 on North bdy., from which
- A Fir 18" dia., bears N.40°E., 15 lks. dist.
 - A Fir 16" dia., bears S.48°E., 50 lks. dist.
 - A Fir 10" dia., bears S.40°W., 24 lks. dist.
 - A Fir 36" dia., bears N.53°W., 50 lks. dist.

Survey by Michael S. McDowell - For: Weyerhaeuser Co. - Feb. 21, 1977 - C.S. File 58/139 and M 63-23

-
- Found 3/4" galv. I.P. placed by Weyerhaeuser Co. Engineers in 1974, (unrecorded), from which
- An 18" Fir stump (OBT) scar evident, bears N.40°E., 9.9 ft
 - A 36" Fir windfall (OBT) face evident, bears N.53°W., 33.0 ft.
 - A 12" Chinquapin RP bears N.76°30'E., 19.9 ft.
 - A 12" Fir RP bears S.15°30'E., 19.8 ft.
 - An 8" Fir RP bears S.52°W., 6.8 ft.
 - An 8" Fir RP bears N.81°W., 27.6 ft.

BLM resurvey by Jack W. Bowder, Cadastral Surveyor, under Group #927, surveyed Aug\Nov. 1977 (DCSO records Vol. 41 Page(s) 16222)

-
- The cor. of secs. 5, 6, 31 and 32, perpetuated and recorded by Weyerhaeuser in 1976, monumented with an iron pipe, 1" dia., firmly set, projecting 6" above ground, from which the remains of the original bearing trees:
- A root hole bears N.53°W., 50 lks. dist., with a down Fir alongside, 36" dia., with healed blaze.
- and the remains of bearing trees mkd. by Weyerhaeuser:
- A sawed Chinquapin stump 12" dia., bears N.76½°E., 31 lks. dist., with illegible scribe marks visible on partially healed blaze.
 - A sawed Fir stump 15" dia., bears S.15½°W., 29½ lks. dist., with healed blaze.
 - A sawed Fir stump 10" dia., bears S.56½°W., 10 lks. dist., with healed blaze.
 - A Fir 12" dia., bears N.79°W., 42 lks. dist., with illegible scribe marks visible on partially healed blaze.

At the corner point
(Cont. Next Page)

