

TOWNSHIP 24 RANGE 09 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Cor. Secs. 32 & 33 (South)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #292, dated Aug 7, 1878 - (DCSO records Vol. 8 Page(s) 3390)

Set maple post 3 ft. long, 5" dia., 18" in ground for the corner to secs. 32 & 33, S. Bdy, from which

- Fir, 60" dia., bears N.2°E., 8 lks.
- Fir, 50" dia., bears S.62°E., 80 lks.
- Fir, 48" dia., bears S.88°W., 100 lks.
- Fir, 85" dia., bears N.85°W., 104 lks.

Tony Hostetter - For: Weyerhaeuser Co. Co. - March 2010 - C.S. File 65/69-9

Found - 3/4" iron pipe in ditch along side 4160 spur (1957 Weyerhaeuser records indicate that 2 original GLO BTs were found. The trees listed in these records do not match GLO descriptions or measurements). All original BTs fall within the Road prism and are gone.

- New BTs- 15" Fir, Weyco tag & spike, bears N.18°E., 29.2 ft. to spike.
- 13" Alder, Weyco tag & spike, bears S.73°E., 23.5 ft. to spike.
- 17" Fir, Weyco tag & spike, bears S.86°W., 27.6 ft. to spike.

CORNER LOCATION: GARMIN 60CSX GPS
43°25'53.8"N
123°46'43.6"W