

TOWNSHIP 24 RANGE 09 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #292, dated Aug 7, 1878 - (DCSO records Vol. 8 Page(s) 3402)

Set maple post, 5 ft long, 5" dia., 18" in ground for the ¼ sec. corner between secs. 23 & 26, from which a
 Fir, 18" dia., bears N.45°E., 19 lks.
 Fir, 24" dia., bears S.35°E., 13 lks.

Tony Hostetter - For: Weyerhaeuser Co. - Sept. 2015 - C.S. File 65/89-65

Found - 2 Weyerhaeuser Co. BTs which were marked in 1970. Weyco corner records indicate that 2 OBTs were fd. Both OBTs have been removed by road construction.
Corner position determined from WEYCO BTs as follows
50" fir stump, WEYCO tag, "W" nail, bears S.60°W., 25.3 ft. to "W" nail.
36" fir stump, WEYCO tag, "W" nail, bears N.20°W., 13.3 ft. to "W" nail.
Note - Weyerhaeuser bearings typically measured by staff compass.
New - No monument set, corner falls in roadway ditch, from calculated position.
15" Fir stump, BT tag, bears N.10°30'E., 13.5 ft. to 6" spike, placed below tag.
13" Fir stump, BT tag, bears S.62°30'W., 19.5 ft. to 6" spike, placed below tag.
19" Fir scribed "S23 ¼ BT", BT tag, bears N.73°W., 31.1 ft. to 6" spike, placed below tag.
Note - New BT bearings determined by hand compass (decl. 18°E)