

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 31 only,

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Resurvey by Joseph A. Ganong and John G. Collins, Cadastral Surveyors, Under special instructions dated March 12, 1921 - (DCSO records Vol. 21 Page(s) 9109)

-----  
Set an Iron post 3 ft. long, 1" dia., 28" in the ground for  
1/4 sec. cor. of sec. 31 only, with brass cap mkd. | 1/4 S31  
1927

from which  
A Fir 14" dia., bears S.28°E., 44 lks. dist. mkd. 1/4 S31 BT  
A Fir 8" dia., bears N.41°E., 6 lks. dist. mkd. 1/4 S31 BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew  
Oct. 1966 - C.S. File 51/30-24

-----  
Found - 1927 GLO brass cap mkd. "1/4 /S31" nearly out of rock mound. We RESET in new mound of stone 2 ft. high. Both 1927 BTs alive and show scar, We Rescribed:  
14" now 18" D.Fir, S.28°E., 29.0 ft. rescribed "1/4 S31 CS BT"  
8" now 13" D.Fir, N.41°E., 4.0 ft. rescribed "1/4 S31 CS BT".

Cor. lies 50 ft. West of Canton Creek, course S. on right high bank and approx. 40 ft. S. of the 1/4 cor. of sec. 36 only, T25S R1W.

Glenn Baughman - For: U.S. Forest Service - Sept. 1980 - C.S. File 58/229-5

-----  
Found - 1927 US GLO brass cap properly mkd., laying on top of the ground. Monument was disturbed by two windthrown trees which pulled it out of the ground.

A 20" D.Fir, orig. BT, with healed blaze, bears S.28°E., 29.0 ft.  
A 12" windthrown D.Fir with healed blaze, bears N.41°E., 4.0 ft.

RESET the monument in its orig. position, 15" in the ground in a 3 ft. dia. mound of stone, 2 ft. high.

New BT - 26" D.Fir bears N.62°E., 104.5 ft. mkd. "1/4 S31 BT" on a double blaze with a brass washer stamped "LS 536" nailed into lower blaze.