

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 30 & 31

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Joseph A Ganong & John G Collins, US Cadastral Engineers under instructions dated March 12, 1921, surveyed May 1927/June 1928 - (DCSO Records Vol. 22 Page(s) 9208)

Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for 1/4 sec. cor., with brass cap marked

1/4 $\frac{S\ 30}{S\ 31}$
1927 from which

A fir, 18" dia., bears S.48°W., 36 lks., mkd: 1/4 S31 BT.
A hemlock, 10" dia., bears N.10½°W., 50 lks. mkd: 1/4 S30 BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage & D West - March 1967 - C.S. File 52/30-76

Found - 1927 GLO brass cap properly marked, out of ground.
Reset - In proper position from the following BTs
Orig. 18", now ___" fir, alive, S.48°W., 23.8 ft., shows good scar. We do not open.
Orig. 10" now 16" hemlock sawed stump, N.10½°W., 33.0 ft. shows "3 BT" scribe on unhealed blaze.
New BT - 6" Chinq. N.26°E., 68.7 ft. mkd. 1/4 S31 CS BT.
Note - Corner lies on N edge of Cat fire trail on S edge of logged unit.

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - April 8, 1986 - C.S. File 62/34-1

Found - A 1927 GLO BC on an IP protruding 11" above ground. 18" now 24" dia. 6 ft. high fallen D.Fir stump with a fully healed single blaze bears S.48°W., 23.8 ft. (agrees with orig.)
10" now 16" dia. 2 ft. high decayed hemlock stump, with a partially healed blaze, scribing visible "S 30 BT" bears N.10½°W., 33.0 ft. (agrees with rec. Orig.)
6" now 10" dia. chinquapin with a partially healed double blaze no scribing visible bears N.26°E., 69.4 ft. (rec. N.26°E. 68.7 ft. to center of trunk) 1967
New BTs- 8" W.Fir double blazed, scribed "1/4 S30 CS BT" bears N.19¼°E., 56.3 ft.
10" W.Fir double blazed, scribed "1/4 S31 CS BT" bears S.30¾°W., 15.9 ft.
8" D. fir double blazed, scribed "1/4 S31 CS BT" bears S.56°W., 34.6 ft.
Corner lies on North edge of fire trail.