

PRIMARY CORNER DESCRIPTION Cor Secs 17, 18, 19, & 20

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Joseph A Ganong & John G Collins, US Cadastral Engineers under instructions dated March 12, 1921, surveyed May 1927/June 1928 - (DCSO Records Vol. 22 Page(s) 9214)

A fir, 10" dia., for cor. of secs. 17, 18, 19, & 20, I mark
T25S S17 on NE
R 1E S20 on SE
S19 on SW, and
S18 on NW, side

from which

- A fir, 10" dia., bears N.35°E., 25 lks., mkd: T25S R1E S17 BT.
- A fir, 6" dia., bears S.58°E., 31 lks., mkd: T25S R1E S20 BT.
- A fir, 10" dia., bears S.53°W., 89 lks., mkd: T25S R1E S19 BT.
- A fir, 8" dia., bears N.65°W., 8 lks., mkd: T25S R1E S18 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage & E. West - April 6, 1967 - C.S. File 52/30-77

- Found - Orig. Corner Tree, 10", now 11" Fir with scars on appropriate side, Now Snag.
- Orig. 8", now 14" Fir, Alive, N.65°W., 5.3 ft., shows good scar.
- Orig. 10", now 13" Fir, shattered Stump, S.53°W. 58.7 ft., reverse scribe.
- Orig. 10", now 14" Fir Snag, N.35°E., 16.5 ft., shows good scar. No trace of SE BT.

Set BC on S. Side of Corner Tree 1 ft. from center Mkd:

County Surveyors	T25S R1E
Office	<u>S 18</u> <u>S 17</u>
1967	S 19 S 20

- New BTs- 10" Fir S. 76°W., 57.7 ft. mkd. T25S R1E S19 CS BT.
- 6" Fir S.77°E., 30.8 ft. mkd. T25S R1E S20 CS BT.
- 8" Fir N.66°E., 15.8 ft. mkd. T25S R1E S17 CS BT.

Note - This corner lies on very steep, SW slope, 50 ft. S. of logging road.