

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Joseph A Ganong & John G Collins, US Cadastral Engineers under instructions dated March 12, 1921, surveyed May 1927/June 1928 - (DCSO Records Vol. 22 Page(s) 9182-3)

Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for 1/4 sec. cor., with brass cap marked

1/4
S 28 | S 27
1927

from which

A hemlock, 12" dia., bears S.76°E., 26 lks., mkd: 1/4 S27 BT
A pine, 10" dia., bears N.26°W., 9 lks., mkd: 1/4 S28 BT.

Leonard Herzstein - Jeremy Goebel - 9/13/2007 - CS 65/60-35

Found - 36" long, 1 1/2" outside dia, iron pipe, laying on the ground, with a 2-5/8" dia. brass cap attached, pre-marked "U.S. GENERAL LAND OFFICE SURVEY" "PENALTY \$250 FOR REMOVAL" and marked as shown. An 8" deephole is alongside the pipe. Area was previously logged about 60 years ago.

From which the remains of the original BT

10" decayed log laying on the ground to the West with scribe marks "1/4 S28 BT" visible on decayed blaze. There is no obvious roothole.

New - As the best remaining evidence, I reset the pipe at the location of the hole. I set the iron pipe 18" in the ground & add a 2 ft dia. mound of stone 8" high. I add marks "RESET 2007" as shown: 1/4

S28 | S27
RESET
2007
1927

New - 16" D.Fir, bears N.84 3/4°E., 4.3 ft, scribed "1/4 S27 BT" on a blaze.

An 18" sugar pine, bears S.0 1/2°W., 8.3 ft. scribed "1/4 S28 BT" on a blaze.

6-ft long alum post, bears N.22°W., 2.0 ft driven 1.5 ft in the ground with Forest Service sign #54-9 "Land Survey Monument" attached.

Note - I used a magnetic declination of 20° East in the staff compass for bearings. Trees are measured to the center of the root crown. Tree diameters are at breast height. The new BTs have a 3/4" brass washer, stamped "LS 2150", nailed flush to the "BT" portion of the blaze. 150 ft from the junction with road no. 3806, the corner is approximately 80 ft East of Forest Service road no. 3806-100.