

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO records Vol. 7 Page(s) 2776½/77

-----  
Set a Cedar post 4 ft. long, 4" sq., 24" in the ground for ¼ sec. cor., mkd. ¼ S on N. face; from which  
A Fir 24" dia., bears S.58°W., 19 lks. dist. mkd. ¼ S BT.  
A Fir 24" dia., bears N.40°W., 6 lks. dist. mkd. ¼ S BT.  
Cor. is on a steep hillside, sloping S. about 75 ft. above creek.

BLM resurvey by Levi E. Tallett and C. Albert White, Cadastral Surveyors, under Group #294, Surveyed May 1951/Aug. 1963 - (DCSO records Vol. 32 Page(s) 13337)

-----  
At the ¼ sec. cor of sec. 31 only, determined at record bearing and distance from the original SW. bearing tree and on line with the old line blazes:  
A Fir 32" dia., bears N.44°W., 60 lks. dist., blaze healed and cut open, edge of blaze under 55 years of overgrowth. (Rec. Fir, bears N.40°W., 6 lks. dist.)  
A Fir 32" dia., bears S.58°W., 19 lks. dist. blaze healed; lower blaze cut open, edge of blaze under 55 years of overgrowth.  
At the corner point  
Set an iron post 36" long, 1" dia., 28" in the ground with brass cap mkd. ¼ S 31  
1951  
from which  
A Fir 14" dia., bears N.4°45'E., 37 lks. mkd. ¼ S31 BT.

Fd. and Used Corner in BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #1061, surveyed April/June 1981 - (DCSO records Vol. 45 Page(s) 17355)

FD. BC & 2 BTs by D. Edwards, 8/2008 - M156-53 - Set 6' steel post 2' north.

Gerald Nygren - For: Barnes & Associates - 12/2018 - M175-10

-----  
Found - 1951 BLM brass cap per rec.  
24" Fir, now 32" snag bears N.44°W., 39.6' healed blaze (1896)  
24" Fir, now blow down root hole bears S.58°w., 12.5' (1896)  
14" fir, now 20' bears N.4°45'E., 24.4' healed blaze (1951)