



PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 4; & 33, T24-1

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM Resurvey by James E. Jelley, Cadastral Surveyor, under Group #'s 350 and 929, Surveyed May 1978/May 1980 - (DCSO records Vol. 42 Page(s) 16338)

-----  
(Corner Report)

The ¼ sec. cor., perpetuated and recorded by Godfrey in 1962, and further perpetuated by Tracy in 1966, monumented with an iron post, 1¼" dia., firmly set, projecting 4" above ground with brass cap mkd. in 1966, from which the remains of an original bearing tree:

A Hemlock snag, 40" dia., bears N.55°W., 17 lks. dist. with scribe marks ¼ S33 BT visible on open blaze. and the remains of a bearing tree mkd. by Godfrey:

A root hole bears N.12°W., 58½ lks. dist., with a down Hemlock alongside, 8" dia., with scribe marks ¼ S33 CS BT visible on open blaze.

and the remains of bearing trees mkd. by Tracy:

A sawed Hemlock stump, 11" dia., bears N.83°E., 91 lks. dist., with a down log alongside, with fragmentary scribe marks visible on open blaze.

A root hole bears S.29°W., 60½ lks. dist., with a down Hemlock alongside, 6" dia., with fragmentary scribe marks visible on open blaze.

No suitable trees available within limits.