

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 360700

PRIMARY CORNER DESCRIPTION E. 1/16 Cor betw. Sec. 4; & 33, T24-1

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

T.E. Shrum, Jr. - For: U.S. Plywood - Nov. 1966 - M 32-62

Set - 2½" dia., alum. cap.  
8" Red Cedar S.70°W., 9.7'.  
6" Hemlock N.76½°E., 24.8'.

Douglas County Surveyors Office - Larry E. Monrean, Deputy,  
P.L. Earle, crew - Dec. 9, 1976 - C.S. File 59/26

Found - 3/4" x 36" steel tube with alum. cap stamped "USPC  
Property Cor. T25S R1W 33, 4 E 1/16 RE 4287"  
Steel tube is bent, cap is 16" above ground.  
Area disturbed by logging.  
An 8" Red Cedar now a stump, bears S.71°W., 14.2  
ft. (Rec. S.70°W., 9.7 ft.) Stump scribed "BT".  
NE. BT not found.

Due to the condition of the monument (bent and loose) and  
the tie to the SW. BT, I determine that the monument has  
been disturbed. I remove the corner monument and place in  
the position where I found it, and I.R., 3/4" x 30" long,  
27" in the ground. I Set monument, marked as noted at  
corner as determined by T.E. Shrum, Jr. in map M 32-62.,  
from which

8" Red Cedar stump bears S.70°W., 9.7 ft.  
3/4" I.Rod bears N.80°E., 4.3 ft.

New Accessory:

Set 3/8" x 12" star drill 10" deep at center of a  
48" Hemlock stump. Marker bears S.41½°W., 31.9  
ft. Stump blazed and scribed "1/16 S4 CS BT".  
Star drill used is a 1/2" drill, shank portion  
measures 3/8".

Fd. OK and used in BLM Resurvey by James E. Jelley,  
Cadastral Surveyor, under Group #'s 350 and 929, Surveyed  
May 1978/May 1980 - (DCSO records Vol. 42 Page(s) 16337-38)