

PRIMARY CORNER DESCRIPTION Sec Cor for 3 & 4; 33 & 34, T24-1

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO records Vol. 7 Page(s) 2780)

 Set a Chinquapin post 4 ft. long, 4" sq., 24" in the ground for cor. of secs. 34, 3, 4, and 33 marked T24S S34 on NE.; R1W S3 on SE.; T25S S4 on SW.; and S33 on NW. faces; with 3 notches on E. and W. edges; from which

- A Fir 48" dia., bears N.18°E., 67 lks. dist. mkd. T24S R1W S34 BT.
- A Fir 6" dia., bears S.29°E., 42 lks. dist. mkd. T25S R1W S3 BT.
- A Fir 48" dia., bears S.35°W., 43 lks. dist. mkd. T25S R1W S3 BT.
- A Fir 36" dia., bears N.24°W., 64 lks. dist. mkd. T24S R1W S33 BT.

Corner is on a steep hillside, sloping E. about 100 ft. below spur.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Nov. 10, 1966 - C.S. File 52/30-58

-
- Found - Orig. 48" now 53" Fir, N.18°E., 44.2 ft., open and find "34" scribe.
 Orig. 6" now 24" Fir, S.29°E., 29.1 ft. (not 27.7 ft.) shows scar.
 Orig. 48" now 58" Fir, S.35°W., 24.4 ft. (not 28.3 ft.) shows scar.
 Orig. 36" now 54" Fir, N.24°W., 42.2 ft., alive, shows good scar.

Set Brass cap at cor. mkd: County Surveyors Office

T24S	R1W	S 33	S 34
T25S		S 4	S 3

 1966

New BTs- 8" W.Fir N.40°W., 8.2 ft. mkd. T24S R1W S33 CS BT.
 8" W.Fir N.56½°E., 13.2 ft. mkd. T24S R1W S34 CS BT
 Corner lies on steep, East slope.

Corner Fd. OK and used in BLM Resurvey by James E. Jelley, Cadastral Surveyor, under Group #'s 350 and 929, Surveyed May 1978/May 1980 - (DCSO records Vol. 42 Page(s) 16337)

Survey by Thomas D. Scherner - For: Woodstock Logging - June 19, 1989 - C.S. File 63/85-23

 Found DCSO monument dated 1966, leaning at 45° angle but not displaced. Straightened monument and placed stones at base.
 (Cont. Next Page)

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 400700

PRIMARY CORNER DESCRIPTION Sec Cor for 3 & 4; 33 & 34, T24-1

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Checked measurements to BTs, found OK.
Found all BTs per notes of DCSO, 1966, with the following exceptions:
 Orig. 48" Fir, now a stump
 Two new BTs by County in 1966, are D.Fir; Orig. 6"
 Fir is a Hemlock.
No new accessories established. Corner is now in recent cut-over.