

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Cor Secs 10, 11, 14, & 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3525)

-----  
Set a fir post, 3 ft. long, 3" sq., 24" in the ground for cor of seCs. 10, 11, 14, & 15, mkd: T25S S11 on NE, R1W S 14 on SE, S15 on SW & S10 on NW, faces with 4 notches on S & 2 notches on E edges, from which  
A Fir, 24" dia. bears N.79°E., 13 lks. mkd T25S R1W S11 BT  
A Dogwood, 3" dia. bears S.70°E. 9 lks mkd T25S R1W S14 BT  
A Chinquapin, 7" dia., bears S.3°W., 25 lks. mkd T25S R1W S15 BT  
A Fir, 18" dia. bears N.65°W., 11 lks. mkd T25S R1W S10 BT

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy - Clete Putnam - June 6, 1962 - C.S. 52/30-8

-----  
Found - ¾" iron reinforcing rod at corner.  
26" D.Fir N.65°W., 7.3 ft. shows 2 very plain axe scars. Did not open.  
32" D.Fir N.79°E., 8.6 ft. shows 2 very plain axe scars didn't open.  
Stump & sprout of Dogwood S.70°E., 5.9 ft.  
No trace of Chinquapin to SW  
New BTs- 16" R.Cedar S.1°W., 22.8 ft. mkd: T25S R1W S15 CS BT  
14" R.Cedar S.26°E. 40.2 ft. mkd: T25S R1W S14 CS BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Nov. 1966 - C.S. File 52/30-54

-----  
Found - ¾" I.Rod buried approx. 14" below surface of ground.  
32" D.Fir N.79°E., 8.6 ft. shows good scars, alive.  
Do not open.  
16" R.Cedar S.1°W., 22.8 ft., shows scribe. Alive.  
14" R.Cedar S.26°E., 40.2 ft. shows good scribe.  
Orig. NW BT lying face down.  
Set - Brass cap at cor mkd: County Surveyors T25S S10|S11 R1W  
over I.Rod Office 1966 S14|S15  
New BT - 10" R.Cedar N.10°W., 60.7 ft. mkd: T25S R1W S10 CS BT.  
Note - This corner lies approx. 100 ft. E of logging access road at a SW corner of timber.  
\*\*NOTE\*\* Cap mkd correctly per BLM 10|11 7/1988 VL  
15|14

continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 10, 11, 14, & 15

Alias	Description

BLM Dependent resurvey by Wayne Rogers, Cadastral Surveyor, under Group #1440, surveyed July/Aug 1988 - (DCSO records Vol. 49 Page(s) 18658-9)

-----  
The cor. of secs. 10, 11, 14 & 15, perpetuated & recorded by Godfrey, in 1962, & further perpetuated & recorded by Tracy, in 1966; monumented with an iron post, 1" dia., firmly set, projecting 8" above ground, with brass cap (properly) mkd., from which the remains of the original bearing trees

A fir, 40" dia., bears N.79°E., 13 lks., with healed blaze.

A root hole, bears N.65°W., 11 lks., with down fir alongside, 26" dia., with healed double blaze.  
and the remains of bearing trees mkd. by Godfrey

A cedar, 18" dia., bears S.28½°E., 61 lks., with fragmentary scribe marks visible on partially healed double blaze.

A cedar snag, 17" dia., bears South, 35 lks., with scribe marks T25S R1W S15 BT visible on open double blaze.  
and the remains of a bearing tree mkd. by Tracy

A sawed cedar stump, 12" dia., bears N.11½°W., 92 lks., with scribe marks T25S R1W S10 visible on open blaze.  
and new bearing trees

A fir, 4" dia., bears S.72°W., 23 lks., mkd. X BT.

A fir, 6" dia. bear N.67½°W., 40 lks. mkd. T25S R1W S10 BT  
From this point, a control point at latitude 43°25'21.81"N and longitude 122°47'01.66"W., established in conjunction with the survey for Group 1347, bears N.7°58'54"W., 83.040 chs., monumented with a finned aluminum rod, 36" long, ¾" dia., firmly set 36" in the ground, in a collar of concrete, with aluminum cap mkd. EC1 G 1347 1987.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 25001006, Surveyed Aug. 2010/April 2011 - (DCSO records Vol. 57 Page(s) 22819)

-----  
The cor. of secs. 10, 11, 14, & 15, monumented with an iron post, 1¼" dia., firmly set, projecting 8" above ground, with a brass cap (properly) mkd.  
from which the remains of the original bearing trees

A fir, 48" dia., bears N.79°E., 8.6 ft., with a healed blaze.

A roothole bears N.65°W., 7.3 ft., downhill of which is an uprooted, decayed fir, 24" dia., with no marks visible.  
and BTs mkd. by Godfrey, in 1962

A cedar, 25" dia., bears S.28½°E., 40.3 ft., with a healed double blaze.

continued next page

TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Cor Secs 10, 11, 14, & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A cedar, 19" dia., bears South, 23.1 ft., with scribe marks TW and other fragmentary scribe marks visible on a partially healed double blaze.  
and the remains of a BT mkd. by the Douglas Co Surveyors Office in 1966, reported by Rogers in 1988  
A sawed, decayed cedar stump, size indeterminate, bears N.11½°W., 60.7 ft., with no marks visible.  
and bearing trees mkd. by Rogers in 1988  
A fir, 10" dia., bears S.72°W., 15.2 ft., with a healed double blaze.  
A fir, 14" dia., bears N.67½°W., 26.4 ft., with a healed blaze.  
Corner is located 250 ft. N. of a dirt road, 10 ft. wide, bears N.20°W. and S.20°E., and 155 ft. E. of the same dirt road, 10 ft. wide, bears N.45°W. and S.45°E.

Adam DeGroot - For: Seneca Jones Timber Co. - July 2020 - M177-19  
-----  
Found a 1½" Iron post by DCSO in 1966 per CS 52/30, firmly set and projecting 8" above the ground, with a 2½" brass cap (properly) marked with accessories as reported per USBLM Dependant resurvey by Kenneth Saveland, group #25001006, plat No. 7625, in 2010/2011  
Lat: 43°24'27.65498"N 122°46'55.52860"W