

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 35 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Hezekiah H. Johnson, Deputy Surveyor, under Contract #721, dated May 1, 1900 - (DCSO records Vol. 8 Page(s) 3501)  
-----  
Set a Arbutus post 3 ft. long, 3" sq., 24" in the ground for 1/4 sec.cor. mkd. 1/4 S35 on N. and S2 on S. faces, from which  
A Fir 14" dia., bears S.6 1/2°E., 27 lks. dist. mkd. 1/4 S2 BT.  
A Fir 15" dia., bears N.70°W., 22 lks. dist. mkd. 1/4 S35 BT

GL0 survey by Fred Mensch, Deputy Surveyor, under Contract #797, dated April 19, 1910 - (DCSO records Vol. 9 Page(s) 3571-72 (and duplicate Pg. 4079)  
-----  
The 1/4 sec. cor. which is a post almost decayed by fire, marked and witnessed as described by the surveyor general. I re-establish the cor. in its original position as the 1/4 sec. cor. on S. bdy. sec. 35, T25S R1W only, as follows:  
Set a basalt stone 15x10x10 ins., 10" in the ground for 1/4 sec. cor. on S. bdy. sec. 35, marked 1/4 on N. face, from which  
A Fir 24" dia., bears N.35°E., 146 lks. dist. mkd. 1/4 S35 BT.  
A Fir 18" dia., bears N.70°W., 22 lks. dist. mkd. 1/4 S35 BT.  
I obliterate marks on former bearing tree referring to sec 2.

Dennis Gaylord, U.S. Forest Service (Deputized by the County) - Sept. 15, 1977 - C.S. File 59/40-13  
-----  
Found - Stone, 15"x10"x10", marked "X" on top and "1/4" on N. face. Stone is firmly set in the ground.  
Orig. 24" D.Fir now 38", bears N.35°E., 69.4 ft. (Rec. 96.4 ft.) with healed blaze.  
Orig. 15" D.Fir now 41", bears N.70°W., 13.5 ft. (Rec. 14.52 ft.) with healed scar.  
Placed DCSO tag on both, which are alive and well.  
Orig. 14" D.Fir now 41", bears S.5°E., 22.8 ft. (Rec. S.6 1/2°E., 17.82 ft.) with healed scar. (Scribing supposedly destroyed by Mensch in 1910). Placed DCSO BT tag on tree.  
Set Brass cap at cor. mkd: County Surveyors Office  
T 25 S R 1 W  
1/4 S 35  
ONLY  
1977  
Buried stone alongside cap. Corner lies 100 ft. East of ridge top and old cat road.

continued next page

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 35 only

Alias	Description

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyors, under Group #1828, surveyed June/July 1997 - (DCSO records Vol. 53 Page(s) 20322-3)

-----

The ¼ sec. cor. of sec. 35 only, on the S. bdy., perpetuated by Gaylord, in 1977, monumented with an iron post, 1½" diam., firmly set, projecting 3" above ground, with brass cap (properly) mkd. from which the remains of an original bearing tree, defaced by Mensch and recorded by Gaylord

A sawed fir stump, 43" diam., bears S.6½°E., 34½ lks., with healed blaze. (Record, 27 lks.)

and the remains of an original bearing tree

A root hole, bears N.70°W., 22 lks., with uprooted fir, 37" diam., alongside, no marks visible.

and a bearing tree mkd. by Mensch

A fir, 40" diam., bears N.29½°E., 105 lks., with healed blaze. (Record, N. 35° E., 146 lks.)

and a new bearing tree

A fir, 26" diam., bears N.66¾°W., 40½ lks., mkd. ¼ S35 BT. The cor. is located at the base of the root-wad from the original NW bearing tree.

From this point, the BLM, Geodetic Control Station No. EC41263, at latitude 43°21'09.370"N., longitude 122°46'13.840"W., (NAD 1983 (91)), determined by the NAVSTAR Global Positioning System, bears N.2°00'19"E., 15.071 chs. (mean bearing and sea level distance), monumented with an aluminum cap, firmly set flush with the ground, with top mkd. EC41263 GPS 1998.

Douglas Co. Surveyors Office - Crew: Stephen Flaue & Jeff Lorsung- 12/7/2022 - C.S. File 67/55-20

-----

Found - Brass cap on 1½" Iron pipe down 2½ ft in tree tip out, dug out now up 2"

Burned out sawn fir stump 33"x4 ft. S.9°E., 22.8 ft. 3½" mag nail left side center (rec. S.6½°E.)

44" D.Fir N.32½°E., 68.2 ft (Rec. N.29½°E., 69.3 ft) 3½" mag nail right side center.

28" D.Fir N.62½°W., 26.7 ft. f(Rec. N.66¾°W.) 3½" mag nail left side center (singed)

New - 5/8"x30" iron rod with DCSO yellow plastic cap up 4" East 44.0 ft. in easterly road shoulder.

Note - Corner is 35 ft. West of spur road running North & East. Corner is on moderate East slope 100 ft.± east of ridge top road.

Compass decl. 14½°E.

Lat: 43°20'59.57" Long: 122°46'14.38"