



TOWNSHIP 25 RANGE 01 POINT IDENTIFIER # 600440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 13 & 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A root hole, bears N.80°W., 55 lks. with down yew  
alongside, 7" dia., tree is buried, no marks found.

At the corner point

Reset iron post, 1½" dia., 30" long, 24" in ground, with  
brass cap incorrectly mkd COUNTY SURVEYORS OFFICE

T 25 S  
¼ S 13 | S 14  
R1W  
1966

and a new bearing tree

A fir, 4" dia., bears N.16½°W., 46 lks., mkd. ¼ S14 BT.

Gerald Nygren - For: Sierra Pacific Industries - 6/2022 -  
M181-9

-----  
Condition report

Found - 1966 BLM brass cap

BT (1960) 32" D.Fir, now 34" stump bears N.40°E.,  
21.78' healed blaze rec. = N.45°E., 22.0'

BT (1966) 12" D.Fir, now 16" stump bears N.4°30'E.,  
24.09' visible scribe rec. = N.5°E., 24 1'

BT (BLM 1988) 4" D.Fir, now 12" bears N.16°30'W.,  
30.36' healed blaze.