

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 7 only, T25-1E

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Resurvey by Joseph A. Ganong and John G. Collins, Cadastral Surveyors, Under special instructions dated March 12, 1921 - (DCSO records Vol. 21 Page(s) 9119)

Set an iron post 3 ft. long, 1" dia., 28" in the ground, for
¼ sec. cor. of sec. 7 only, with brass cap mkd. ¼ S7

1927

from which

A Fir 24" dia., bears N.49°E., 71 lks. dist. mkd. ¼ S7 BT.

A Fir 50" dia., bears S.51°E., 65 lks. dist. mkd. ¼ S7 BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Oct/Nov. 1966 - C.S. File 52/30-42

Found - 1927 GLO brass cap mkd. "¼ S7", firmly set.
24" now 26" Fir with top broken out, N.49°E., 46.9
ft., alive, shows good scar. We do not open.
50" now 52" Fir, uprooted and out of position,
S.51°E., 49.2 ft.

New BTs- 51" D.Fir stump, S.78°E., 27.2 ft. mkd. ¼ S7 CS BT

42" D.Fir stump N.2°E., 14.0 ft. mkd. ¼ S7 CS BT.

Corner lies approx. 60 ft. S. of cutting corner in clear cut
unit and 146 ft. S. of ¼ cor. Sec. 12, T25S R1W.

Kristian DeGroot - For: U.S. Forest Service - May 1992 - C.S.
File 63/138-20(D)

Found - 1" Iron pipe with 1927 GLO brass cap, firmly set,
flush with the ground. Cap properly mkd.
30" broken top D.Fir, bears N.50°E., 47.5 ft., with
a healed blaze. (Rec. N.49°E., 71 lks.) 1927
52" uprooted D.Fir bears S.46°E., 43.0 ft. with a
burned blaze. (Rec. S.51°E., 65 lks.) 1927
42" D.Fir stump bears N.2°E., 14.0 ft. with scribe
marks "¼ S7 CS BT" visible.
48" D.Fir stump, bears S.78°E., 27.2 ft. with scribe
marks "¼ S7 CS BT" visible.

New BT - 10" D.Fir bears S.59°E., 33.8 ft. scribed "¼ S7 BT."