

PRIMARY CORNER DESCRIPTION E. 1/4 cor. for Sec. 1 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Carl S. Nicklin, Deputy Surveyor, under joint contract #664 dated May 23, 1896 (DCSO records Vol. 8 Page(s) 3482)

Set a Madrona post, 4 ft. long, 4" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on W. face, from which
A Fir 24" dia., bears S.50°E., 96 lks. dist. mkd. 1/4 S BT.
A Chinquapin 6" dia., bears S.35°W., 23 lks. dist. mkd. 1/4 S BT.
This cor. is on a hillside, sloping SW.

GLO resurvey by Joseph A. Ganong and John G. Collins, Cadastral Surveyors, under Instructions dated March 12, 1921 - (DCSO records Vol. 21 Page(s) 9122)

The 1/4 sec. cor. established for secs. 1 and 6, which is a badly decayed madrona post with marks illegible. I now change this cor. to refer to sec. 1 only. In place of the decayed post, Set an iron post 3 ft. long, 1" dia., 28" in the ground, for 1/4 sec. cor. of sec. 1 only, with brass cap mkd.

1/4 S1
|
1927 from which
A Fir 30" dia., bears S.50°E., 96 lks. dist., old BT, the marks on which I now destroy.
A Chinquapin 14" dia., bears S.35°W., 23 lks. dist., old BT, with marks grown over.
A Pine 8" dia., bears N.62°W., 22 lks. dist. mkd. 1/4 S1 BT. (New BT)

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Oct/Nov. 1966 - C.S. File 52/30-50

Found - 1927 GLO brass cap, firmly set and properly marked. Orig. 30" Fir now snag, S.50°E., 63.4 ft. This BT was obliterated in 1927, rehealed blaze. Use as reference since bearing to fallen BT does not check.
8" now 14" Pine, N.76°W. (not N.62°W) 14.5 ft., partial scribe marks visible on nearly healed blaze. Alive. Rescribe "1/4 S1 CS BT".
8" now 14" chinquapin, S.35°W., 15.2 ft., fragmentary scribe marks visible on badly decayed and unhealed blaze. Alive.
New BT - 12" D.Fir S.6°W., 22.5 ft. mkd. 1/4 S1 CS BT.
Cor. lies 25' E. of new logging rd., course N-W., curving SE.