

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 100142

PRIMARY CORNER DESCRIPTION East 1/4 Corner Sec 36 only, T25-3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

(Original 1/4 Corner for 36 and 31 of T.25-2 set by Laban Wheeler, Contract #467, 1883) DCS0 records, Volume 9 Pg 3585

GL0 Dependent Resurvey by Norman D. Price, Under Special Instructions dated April 5, 1940 (DCS0 rec, Vol 27 Pg 11509)

Proportional measurement - Set an iron post 3 ft. long, 1 in. diam., 28 ins. in the ground, for 1/4 sec. cor. of sec. 36 only, with brass cap marked:

¼ S36
1943 from which

A Fir, 9" dia., bears S.8½°W., 7 lks., marked ¼ S 36 BT.
A Fir 13" dia. bears N.38°W., 9 lks., marked ¼ S 36 BT.

Doug. Co. Surveyors Office - Vernon Tracy; Joe Brady; Jack Heritage - June 1966 - C.S. File 54/27-171

Found - 1943 GL0 brass cap marked and in good condition.
9" Fir, now stump 2 ft. high, S.8½°W., 4.6 ft. (face), "¼S36 BT" on burned face.
13" Fir, turned out, N.38°W., 5.9 ft. face burned, fragmentary scribe visible.
New BTs - 5" D.Fir S.73°W., 38.9 ft. mkd. ¼ S36 CS BT.
7" Hemlock N.23°W., 22.4 ft. mkd. ¼ S36 CS BT.
Corner lies 25 ft. North of top of small spur sloping S.60°E.

Fd. and used - BLM Dependent Resurvey, 1972-75 (DCS0 records, Volume 36 Page 15110)

Doug. County Surveyors Office - Randall Smith, Deputy; Stephen Flause - August 10, 1992 - C.S. File 64/32-2

Found - 2½" dia. GL0 brass cap on a 1" O.D. Iron pipe, protrudes 1 ft. above ground.
9" now 9" dia., 2 ft. high rotted D.Fir stump, no blazes or scribing found, bears S.8½°W., 4.6 ft. (agrees w/record) (1943 GL0)
13" now 13" dia. down and rotted D.Fir, no blazes or scribing found, bears N.38°W., 5.9 ft. (agrees w/record) (1943 GL0)
7" now 13" dia. 2 ft. high Hemlock stump with a fully healed double blaze, bears N.23°W., 22.4 ft. (agrees w/record) (1966 DCS0)
SW BT from 1966 DCS0 renewal is gone.
BLM 1972 BC/IP (W ¼ S31 T25S R2W only) bears South 73.9 ft. (agrees w/record)

Continued next page

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 100142

PRIMARY CORNER DESCRIPTION East 1/4 Corner Sec 36 only, T25-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New BTs- 14" dia. D.Fir double blazed and scribed "¼ S36 CS BT" bears S.2½°W., 39.1 ft.
12" dia. D.Fir double blazed and scribed "¼ S36 CS BT" bears S.45½°W., 40.5 ft.
4" dia. Madrone bark scribed "¼ S36 CS BT" bears S.53°W., 3.6 ft.
14" dia. Alder bark scribed "¼ S36 CS BT" bears N.26½°W., 20.8 ft.

Fd. Ok by D.Edwards, 4/1998 - M128-61

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2919, surveyed May 2018/July 2020 - (DCSO records Vol. 59 Page(s) 23919-20)

The ¼ sec. cor. of sec 36 only T25S R3W perpetuated by Smith, in 1992, monumented with an iron post, 1" dia., firmly set, projecting 13" above ground, with a brass cap (properly) mkd. from which the remains of the BTs mkd. by Price in 1943-44

A decayed fir stump, 11" dia., bears S.8½°W., 4.6 ft., no marks visible.

A roothole bears N.38°W., 5.9 ft., alongside of which is a down decayed fir, 10 ins. diem., no marks visible and a broken top.

and the remains of the BTs mkd by the Douglas Co. Surveyors Office in 1966, reported by Berry, Wofford, Popken, and Baughman in 1972-75

A decayed fir stump, 16" dia., bears S.76°W., 39.6 ft., with a healed blaze

A decayed hemlock stump, 16" dia., bears N.22°W., 22.4 ft. no marks visible.

and the remains of the bearing trees mkd. by Smith

A fir stump 21" dia., bears S.3¾° W., 39.3 ft., with a healed double blaze.

A decayed fir stump, 17" dia., bears S.46¼°W., 40.6 ft. no marks visible.

A madrone snag, 4" dia., bears S.55¼°W., 3.4 ft., with scribe marks ¼ S36 BT visible on bark.

and new bearing trees

The northerly stern of a twin trunk hemlock, 4" dia., bears S.79¾°W., 43.8 ft. mkd. X BT

A cedar, 11" dia., bears N.44½°W., 26.9 ft. mkd. ¼ S36 BT
Each new BT has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center & each monument established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post. Alum. Angle iron driven alongside each monument.

_____cont.

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 100142

PRIMARY CORNER DESCRIPTION East 1/4 Corner Sec 36 only, T25-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 3/1/2023 - C.S. File 67/55-57

Found - BLM brass cap (properly mkd) up 13"
Burned fir stub 20"x1 ft. S.46¼°W., 40.6 ft., no marks visible.
Burned, madrone stub 4"x1½ ft., S.55¼°W., 3.4 ft., blaze burned off.
Burned, dead 11" Cedar N.44½°W., 26.9 ft., blaze vis scribes burnt off. 2½" mag nail right side center
Sawn, burned 21"x7 ft. D.Fir stump, S.3¾°W., 39.3 ft., healed double blaze, add 3½" mag nail right side center.
Note - On large bench recent logging to West, burnt forest to East.
Area burnt, 9/2020
Compass decl. 14½°E.
Lat: 43°21'05.89" N Long: 122°59'26.04" W