

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION C C for Secs. 31 and 32 only (South)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Hezekiah H. Johnson, Deputy Surveyor, under Contract #721, dated May 1, 1900 - (DCSO records Vol. 9 Page(s) 3640)

At point of intersection (7.59 chs. N.89°45'W of the cor. of 5, 6, 31 and 32), I Set a basalt stone 18x8x6 ins., 12" in the ground for closing cor. of secs. 31 and 32, mkd. CC with 5 notches on E. and 1 notch on W. edges, from which
A Cedar 6" dia., bears N.15°E., 28 lks. dist. mkd. T25S R2W S32 BT.
A Hemlock 4" dia., bears N.52°W., 17 lks. dist. mkd. T25S R2W S31 BT.

V.W. Hosford, For: Evans Products Co. - Feb/Oct. 1960 - C.S. File 51/144 & M19-77

I could find no evidence of the corner described in survey of 1900. At the point of the corner, I Set a 4" Fir post, mkd. CC 31 and 32, from which
21" Cedar bears N.67°E., 20.3 ft. mkd. CC S32 253 BT.
25" Cedar bears N.68°W., 27.8 ft. mkd. CC S31 253 BT.
Corner is 20 ft. South of ridge top between Rock Creek and North Umpqua River.

Douglas County Surveyors Office - John M. Powell, Ed Monrean, crew - July 1972 - C.S. File 54/40-201

Found - 21" Cedar N.67°E., 20.3 ft., some scribing visible.
25" now 28" Cedar N.68°W., 27.8 ft., shows good scar.
4" Fir post at cor. mkd. CC S31 & S32.
Set Brass cap at C.C. mkd. County Surveyors Office 1972
T 25 S R 2 W
C C
S 31 | S 32
S 6
T26S

Bearing trees OK, and tagged.

Fd. Cor. OK and used in BLM Resurvey by Daniel Berry; Harvey Wofford; G. Steven Popken, Cadastral Surveyors, under Group #'s 786, 848 and 854. And Glenn S. Baughman, L.S. #536, under Contract #52500-CT5-1116, Surveyed July 1972/Oct. 1975 - (DCSO records Vol. 36 Page(s) 15107-08)

(Cont. Next Page)

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION C C for Secs. 31 & 32 only (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Frank O. Williams & Glen McChesney - For: Weyerhaeuser Co. -
April 28, 1976 - C.S. File 58/8-42

Found - 21" now 22" I.Cedar bears N.68°E., 21.1 ft.,
scribing visible.
25" now 28" I.Cedar bears N.68°W., 28.3 ft., face
healed over. (to center of tree)
Hosford's 4" Fir post, down.
1972 DCSO brass cap and BT tags.
New BT - 48" Fir bears S.70°W., 12.3 ft. with "W" nail and
plate.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral
Surveyor, under Group No. 2919, surveyed May 2018/July 2020 -
(DCSO records Vol. 59 Page(s) 23915)

The closing cor. of secs. 31 & 32, T25S R2W perpetuated by
Williams, in 1976, monumented with an iron post, 1¼" dia.
firmly set, projecting 16" above ground, with a brass cap
(properly) mkd.
from which the remains of the BTs mkd. by Hosford, in 1960,
reported by Berry, Wofford, Popken, and Baughman in 1972-75
A cedar, 36" dia., bears N.67°E., 19.8 ft., with a healed
blaze.
A decayed cedar stump, size indeterminate, bears N.68°W.,
28.4 ft., no marks visible.
and the remains of a bearing tree mkd. by Williams
A decayed fir stump, 54" dia., bears S.69¼°W., 14.6 ft.,
with axe marks visible.
and a new bearing tree
A fir, 12" dia., bears N.50¼°W., 28.9 ft., mkd. T25S R2W
S31 BT.

Corner is located S., 85 ft. dist. of a graveled road, 20 ft.
wide, bears East and S.75°W.
Each new BT has a 2½"x ¼" magnetic nail (Mag Nail) driven at
the base right side-center & each monument established or
remonumented has a magnet deposited in a white plastic case
at the base of the stainless steel post. Alum. Angle iron
driven alongside each monument.

NAD 1983 (2011)

Lat: 43°20'37.47" N Long: 122°58'24.38" W

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff
Lorsung- 9/19/2022 - C.S. File 67/54-20

Found - 2½" DCSO brass cap on 1¼" I.pipe up 18" in rough
mound of stone.

Continued next page

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION C C for Secs. 31 and 32 only (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

30"x4½" burnt-sawn cedar stump N.67°E., 21.0 ft.
(Rec. 19.8 face meas) heal single blaze, add 3½"
mag nail. Right side center. 1960
Very burnt & rotted 38"x3' stump S.69¼°W., 14.6 ft.
1960
Burnt-sawn 14"x1' fir stump N.50¼°W., 28.9 ft. with
burnt blaze. BLM
Alum angle iron post alongside.
Note - Corner is 85±' south of gravel road East & S.75°W.
Area burnt 9/2020
Lat: 43°20'37.46"N Long: 122°58'24.42"W