

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 5

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3638)

-----

Set basalt stone 16x8x6", 11" in the ground for ¼ sec. cor. marked ¼ on W face, from which

A hemlock, 16" dia., bears S.51°E., 3 lks., mkd: ¼ S4 BT.

A cedar, 28" dia., bears N.77°W., 40 lks., mkd: ¼ S5 BT.

BLM dependent resurvey Levi E Tallett, Cadastral Engineer (1951) and C. Albert White, Cadastral Surveyor (1963), under Group # 294, surveyed May 1951 - Aug 1963 - (DCSO records Vol. 32 Page(s) 13352)

-----

The ¼ sec. cor. of secs. 4 & 5, monumented with a basalt stone, 18x8x6", firmly set, marked ¼ on W face, from which the original bearing trees:

A cedar, 40" dia., bears N.79°W., 42 lks., blaze rotted and chopped open, scribe marks ¼ S5 visible. (Record: bears N.77°W., 40 lks.)

A hemlock, 16" dia., bears S.44°E., 3 lks., blaze chopped partially open. (Record bearing, S.51°E.)

At the corner point

Set an iron post, 36" long, 1" dia., 28" in the ground, with brass cap mkd.

¼  
S 5 | S 4  
1951

from which

A hemlock, 8" dia., bears N.45°W., 57 lks., mkd. ¼ S5 BT.

Bury the original corner stone alongside the iron post.

Ron Quimby - Crew: L. Heddens & J. Ogden - 10/2020 - C.S. File 65/106-41

-----

Found - BLM brass cap (properly marked)  
Roothole S.44°E., 1.98 ft (tree lost in fire)  
Other tree of record lost in fire.

Set - 5/8"x30" I.Rods with yellow plastic cap mark ie engineering with alum post along side.  
N.75°E., 7.4 ft.  
S.32°E., 16.7 ft.  
S.48°W., 16.0 ft.  
N.52°W., 14.7 ft.

Note - Area badly burnt 9/2020  
Compass decl. 15½°E.