

PRIMARY CORNER DESCRIPTION Corner Parcels 41 & 42 (W line Sec 4)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM dependent resurvey Levi E Tallett, Cadastral Engineer (1951) and C. Albert White, Cadastral Surveyor (1963), under Group # 294, surveyed May 1951 - Aug 1963 - (DCSO records Vol. 32 Page(s) 13352-3)

Corner of parcels 41 & 42, sec. 4, as shown in Court Decree "Civil No. 60-135, Oregon". The corner is monumented with an iron pipe, 24" long 3/4" dia., firmly driven 18" in the ground from which

A fir, 33" dia., bears N.45 1/4°E., 10 lks., mkd: P41 S4 BT.

A fir, 70" dia., bears S.34 3/4°E., 98 lks., mkd: P42 S4 BT.

Glen McChesney, WEYCO - 12/20/1975 - C.S. File 59/46-78

Found - 3/4" IR not found, apparently buried under turned up roots of down fir.

32" fir, down, scribed face, N.45°E., 6.6 ft. to center of root hole.

60" fir stump, scribed face, BLM BT tag, bears S.35°E., 64.7 ft., center measurement.

New - 3" sq. yew post.

44" Fir bears N.65°E., 47.8 ft. "W" nail & Weyerhaeuser company plate low on tree.

Douglas Co. Surveyors Office - Gary Langlitz, Stephen Flause, & Frank Silagy - 4/3/1978 - C.S. File 59/46-78

Found - 3/4" Iron pipe, set by Cadastral Surveyor in 1963 not fd., probably displaced by nearby uprooted tree.

A 70" D.Fir, now a stump with scribing "P42 S4 BT: visible on unhealed blaze bears S.34 3/4°E., 64.7 ft

A 33" D.Fir, now a windfall with scribing "P41 S4 BT" bears approx. N.45°E., 6.6 ft.

New - At a location which agrees with the previously described corner we set a 5/8"x30" iron rod 27" in the ground with aluminum cap attached marked:

DOUGLAS CO. SURVEYOR 1978

|P 41

|P 42

1978

Also fd- A "W-nail" set in the base of a 44" D.Fir stump, N.65°E., 47.8 ft. to the nail.