

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Hezikiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3635)

Set basalt stone 14x12x4", 10" in the ground for ¼ sec. cor. marked ¼ on N face, from which

A fir, 20" dia., bears N.27°E., 4 lks., mkd: ¼ S9 BT.

A hemlock, 5" dia., bears S.30°W., 6 lks., mkd: ¼ S16 BT.

BLM dependent resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #350, surveyed April 1962 -(DCSO records Vol. 32 Page(s) 13234-5)

The sec. cor. of secs. 9 & 16, monumented with a basalt stone, 14x32x4", firmly set 10" in the ground, marked ¼ on the N face, from which the original bearing trees:

A fir, 32" dia., bears N.27°E., 4 lks. with a healed blaze.

A broken hemlock stump, 7" dia., bears S.30°W., 6 lks., with scribe mark 4 visible on opened blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 24" in the ground & in a mound of stone, 2 ft. base, to top, with brass cap mkd

¼ $\frac{S \ 9}{S \ 16}$

T25S R2W

1962

from which a new bearing tree

A hemlock 12" dia., bears S.44°W., 106 lks., mkd S16 BT.

Deposit the original corner stone alongside the iron post.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West- March 1967- C.S. File 54/27-120

Found - 1962 cad. brass cap, properly mkd.

Orig. 32" now 33" fir, alive N.27°E., 2.6 ft shows good scar. Do not open.

Orig. broken Hemlock stump 7" dia., S.30°W., 4.0 ft. with "4" scribe visible.

No trace of BT marked in 1962 due to logging.

New BT - 8" Hemlock S.6½°E., 95.5 ft. mkd: ¼ S16 CS BT.

Note - This corner lies on SW slope in logged off unit.

Douglas Co. Surveyors Office - Rod Kimberling - Pete Earle - Michael Cline - Aug. 31, 1977 - C.S. File 59/38-23

Found - BLM brass cap (properly mkd) on a 2" dia. iron pipe buried at a 45° angle under a 34" dia., D. Fir log.
continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 16

Alias	Description

A stone, 14"x12"x4" now 14"x9"x4" (broken in resetting) at the south side of brass cap with "¼" chiseled on N face. Other stones found around iron pipe.

A 20" now 34" dia., D.Fir, uprooted & laying across brass cap. Blaze apparently on ground side, Center of root hole bears approx. N.27°E., 2.6 ft

An 8" hemlock snag bears S.6½°E., 96.2 ft. (Rec. 95.5 ft.) blazed and marked "¼ S16 CS BT. 1967

New - Cut away section of log & straightened iron pipe with brass cap at ground level. Stamped "Reset 1977" above 1962.

Reset chiseled stone at north side of brass cap.

A 6" dia., D.Fir bears N.54°W., 44.4 ft., double blazed & marked "¼ S9 T25S R2W CS BT.

A 5" dia., D.Fir, bears S.22°E., 14.6 ft., double blazed & marked "¼ S16 T25S R2W CS BT."

Set a boat spike on root wad directly above brass cap. Stamped "BO No. 1"

BLM Dependent resurvey by Richard J. Dieckmann, Cadastral Surveyor, under Group No. 2749 , surveyed Aug. 2014/April 2015 - (DCSO records Vol. 58 Page(s) 23340-1)

The ¼ sec. cor. of secs. 9 and 16, perpetuated by the Douglas County Surveyor's Office in 1967 and 1977, monumented with an iron post, 2½" dia., firmly set, buried 3" below the ground, with a brass cap (properly) mkd. from which the remains of BTs mkd. by the Douglas Co Surveyor's Office in 1977

A D.Fir stump, 16" dia., bears S.22°E., 14.6 ft., with a healed blaze.

A D.Fir, 25" dia., bears N.55¾°W., 44.4 ft., with a healed blaze.

and a new bearing tree

A D.Fir, 14" dia., bears N.63°E., 16.4 ft., mkd. ¼ S9 BT.