

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 10

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3624)

-----

Set basalt stone 16x10x8", 11" in the ground for ¼ sec. cor. marked ¼ on W face, from which

A yew, 8" dia., bears S.56°E., 45 lks., mkd: ¼ S10 BT.

A yew, 8" dia., bears N.75°W., 20 lks., mkd: ¼ S9 BT.

N.2'W., 2.03 chs.

A Fir, 36" dia., on line, I mark w/2 notches on N & S sides.

BLM dependent resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #350, surveyed April 1962 -(DCSO records Vol. 32 Page(s) 13229)

-----

The ¼ sec. cor. of sees. 9 & 10, monumented with a basalt stone, 16x10x8", firmly set 11" in the ground, marked ¼ on the W face, from which the original bearing trees:

A down yew, 11" dia., bears S.56°E., 45 lks., with no marks remaining.

A down yew, 8" dia., bears N.75°W., 20 lks., with no marks remaining.

At the corner point

Set an iron post, 25" long, 2½". dia., 26" in the ground, with brass cap mkd:

¼  
S 9 | S 10  
T25S R2W  
1962

from which new bearing trees

A cedar, 32" dia., bears S.45½°E., 91 lks., mkd ¼ S10 BT.

A hemlock 27" dia., bears N.26°W., 100 lks., mkd ¼ S9 BT.

and an original line tree

A fir, 92" dia., bears North, 203 lks., mkd with 2 notches on the N & 2 notches on the S side,

Deposit the original corner stone alongside the iron post.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy & Crew - June 26, 1972 - C.S. File 54/27-127

-----

Found - 1962 Cadastral Brass Cap, in place & properly mkd. Orig. Corner Stone Mkd: "¼" set on S Side of B.C. Orig. 8" now 12" Yew N.75°W., 13.2 ft. broken, dead. No scribe.

27" now 28" Hemlock N.26°W., 66.0 ft., alive, good scribe "¼ S9 BT" visible.

32" Cedar, now snag, S.45½°E., 60.1 ft., bent over by large Fir log.

New BT - 36" cedar N.1°E., 20.0 ft. scribed "¼ S10 CS BT"

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 10

Alias	Description

Note - Old line tree N. 135.0 ft., now 80 ft. high snag, notches on N. & S. Sides visible.  
This corner lies on very steep southerly slope in canyon.

Fd. BC, 2 BTs & stump found on line north of corner (N.2°15'35"E., 136.0 ft.) 2/1992, M114-57

BLM Dependent resurvey by Richard J. Dieckmann, Cadastral Surveyor, under Group No. 2749 , surveyed Aug. 2014/April 2015 - (DCSO records Vol. 58 Page(s) 23337-8)

-----  
The ¼ sec. cor. of secs. 9 and 10, perpetuated by the Douglas Co Surveyor's Office in 1972, monumented with an iron post 2½" dia., firmly set, projecting 1" above the ground, with a brass cap (properly) mkd.  
from which the BT mkd. by the Douglas Co Surveyor's Office  
A cedar, 40" dia., bears N.1¼°E., 20.5 ft., with scribe marks ¼ S10 visible on a partially healed upper blaze and scribe marks CS BT visible on a partially healed lower blaze.  
and a new bearing tree  
A D.Fir, 8" dia., bears N.74¾°W., 27.4 ft., mkd. ¼ S9 BT.  
The original stone is set along the S. side of the iron post.

Ron Quimby - Crew: L. Heddens & J. Ogden - 10/2020 - C.S. File 65/106-46

-----  
Found - BLM Brass cap (properly mkd)  
40" burnt cedar N.1¼°E., 20.5 ft (burnt scribe)  
12" burnt fir N.74¾°W., 27.4 ft healed scar.  
Set - 5/8"x30" I.Rods with yellow plastic cap stamped ie engineering:  
N.21°E., 32.7 ft. }  
S.33°E., 22.0 ft. } Post set alongside of I.Rods  
N.82°W., 16.9 ft. }  
N.41°W., 25.0 ft. }  
Note - Area badly burnt 9/2020.  
Corner is approx 450' south of road  
Compass decl. 15½°E.