

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3621)  
-----  
The point for ¼ sec. cor. falls on a basalt stone in place 24x10x6", above the ground at the exact cor. point I marked a cross (X) & ¼ to N of cross for ¼ sec. cor., from which  
A hemlock, 12" dia., bears N.39°W., 7 lks., mkd: ¼ S15 BT.  
A cedar, 8" dia., bears S.18°E., 32 lks., mkd: ¼ S22 BT.

V.W. Hosford - Oct. 18, 1957 - C.S. File 42/308-7  
-----  
At this corner I found a stone answering the description of the orig. corner stone. However, I could find no marking on it, probably due to erosion.  
The orig. BT for sec. 15 is in good condition, for sec. 22 a dead snag.  
I drove a 1½" iron pipe 36" long, 24" in the ground at the south edge of the corner stone & marked new BT for sec. 22  
From the point of the corner  
A Hemlock 30" dia., bears S.55°W., 21.7 ft. mkd ¼S 22 253 BT

BLM dependent resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #350, surveyed April 1962 - (DCSO records Vol. 32 Page(s) 13227)  
-----  
The ¼ sec. cor. of secs. 15 & 22, monumented with a basalt stone, 24x10x6" above ground, marked X on top & ¼ on the N face, perpetuated & recorded by Hosford in 1957 by driving an iron pipe, 36" long, 1½" dia., 20" in the ground, alongside corner stone, from which the original bearing trees:  
A hemlock, 18" dia., bears N.39°W., 8 lks., with fragmentary scribe marks visible on partly healed blaze (Record distance, 7 lks.)  
A cedar snag, 13" dia., bears S.15°E., 32 lks., with no marks remaining on rotted blaze. (Rec bearing, S.18°E.)  
and a bearing tree marked by Hosford  
A hemlock, 30" dia., bears S.54½°W., 33 lks., with scribe marks ¼ S22 253 BT visible on unhealed blaze.  
At the corner point  
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked  
¼  $\frac{S\ 15}{S\ 22}$   
T25S R2W  
1962  
Deposit the original corner stone and reset iron pipe alongside the iron post.

continued next page

1

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 22

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Douglas Co. Surveyors Office - Randall Smith, Stephen Flause;  
Sept. 26, 1996 - C.S. File 65/9-19

- 
- Found - 3¼" dia. brass cap on a 2½" O.D. iron pipe, protrudes 3" above ground. (1962 BLM)  
1½" I.D. iron pipe, protrudes 13" above ground, along NE'ly edge of BC/IP  
A broken stone that measures 24" x 10" x 6". No marks found. Stone is along north edge of BC/IP. (orig. cor. stone)  
30" now 29" dia. 15 ft. high Hemlock snag with scribing visible on an unhealed blaze "¼ S22 53 BT", bears S.54½°W., 21.8 ft. (agrees with rec.)  
12" now 23" dia. 3 ft. high Hemlock stump, scribing fd "¼ S1" and a healed blaze, bears N.39°W., 5.3 ft. (agrees with rec.)  
8" now 10" dia. 25 ft. high Cedar snag with a rotted blaze, no scribing visible, bears S.15°E., 21.1 ft. (agrees with rec.) O.B.T.
- New - 7" dia. Cedar, double blazed and scribed "¼ S15 CS BT" bears N.42°W., 7.0 ft.  
12" dia. D.Fir, double blazed and scribed "¼ S22 CS BT" bears S.26½°E., 11.6 ft.  
5" dia. D.Fir, double blazed and scribed "¼ S15 CS BT" bears S.38°W., 22.5 ft.

BLM resurvey by A. Bert Skeesick, Cadastral Surveyor under Group #1979, surveyed May 2001/June 2002- (DCS0 rec. Vol. 54 Page(s) 20926-7)

-----

The ¼ sec. cor. of secs. 15 & 22, monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with orig. stone lying alongside, and an iron pipe, 1½" dia., driven alongside, with brass cap (properly) mkd. from which the remains of the original bearing trees

- A cedar snag, 10" dia., bears S.12°E., 21.1 ft., with no marks visible on decayed blaze. (Record, S.15°E.)
- A decayed hemlock stump, 26" dia., bears N.36°W., 4.6 ft., with illegible scribe fragments lying alongside. (Record, N.39°W.)

and remains of BT mkd by Hosford, in 1957, reported by Brooks

- A decayed hemlock snag, 29" dia., bears S.56°W., 21.8 ft., with fragmentary scribe marks visible on open blaze and large X hacked into the bark on the side away from the corner. (Record, S.54½°W.)

and bearing trees mkd. by Smith & Flause, in 1996

- A fir, 13" dia., bears S.21¼°E., 11.6 ft., with healed double blaze.

continued next page

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 22

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

A fir, 6" dia., bears S.37°W., 22.9 ft., with fragmentary scribe marks visible on partially healed double blaze.  
A cedar, 10" dia., bears N.40¾°W., 7.7 ft., with fragmentary scribe marks visible on partially healed double blaze.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 10/5/2022 - C.S. File 67/54-22

-----  
Found - 3¾" brass cap on 2½" O.D. I.Pipe up 8", orig stone along side. 1½" I.Pipe on E edge up 20", rough mound of stone.  
Rotted & burnt 14"x1½ ft Fir stump S.24½°E., 11.6 ft. (BLM rec. S.21¾°E.) 1996  
Burnt-dead 16" cedar N.40¾°W., 7.7 ft., add 3½" mag nail right side center. 1996  
Alum post NNE 1 ft.  
New - 8" mag spike in root of 14"x1½' burnt and rotted fir stump S.28½°E., 11.7 ft. 1996 SE BT.  
5/8"x30" I.Rod with DCS0 yellow plastic cap S.24¾°W., 94.0 ft, up 15" in westerly road shoulder.  
5/8"x30" I.Rod with DCS0 yellow plastic cap S.76½°W., 75.5 ft in westerly road shoulder up 6"  
Note - Area burnt 9/2020  
Compass decl. 14½°E.  
Corner is approx. 35 ft higher and 55' east of  $\perp$  of gravel road.  
Lat: 43°23'17.29"N Long: 122°55'25.49"W