

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 11

| Alias | Description |
|-------|-------------|
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |
| _____ | _____ |

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3613)

Set a basalt stone 16x8x6", 11" in the ground for 1/4 sec. cor. marked 1/4 on N face, from which
A fir, 24" dia., bears N.19°E., 46 lks., mkd: 1/4 S2 BT.
A hemlock, 5" dia., bears S.35 1/2°W., 15 lks., mkd: 1/4 S11 BT

BLM dependent resurvey Levi E Tallett, Cadastral Engineer (1951) and C. Albert White, Cadastral Surveyor (1963), under Group # 294, surveyed May 1951 - Aug 1963 - (DCSO records Vol. 32 Page(s) 13344)

The sec. cor. of sees. 2 & 14, monumented with a basalt stone, 14x8x6", firmly set, marked on N face, from which the original bearing trees:
A fir, 42" dia., bears N.18°45'E., 46 lks., blaze healed. (Record bearing, N.19°E.)
A hemlock, 10" dia., bears S.40°W., 15 lks., blaze healed. (Record bearing, S.35 1/2°W.)
At the corner point
Set an iron post, 36" long, 1" dia., 28" in the ground, with brass cap mkd.
1/4 S 2 / S 11 / 1951
No new accessories established.
Bury the original corner stone alongside the iron post.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy & Crew - Feb. 1966 - C.S. File 49/102-12

Found - 14x8x6" basalt stone mkd: "1/4" & GLO brass cap, 1951
Orig. 42" D.Fir N.18 3/4°E., (face) now stump, shows good scar & has "W" nail at base.
Orig. 10" Hemlock S.40°W., 9.9 ft., down & badly rotted, fd. "BT"
30" D.Fir stump S.13°E., 54.9 ft with "W" nail & tag
New BTs- 10" W.Fir, N.31 1/2°W., 30.0 ft. mkd: 1/4 S2 CS BT
14" R.Cedar S.37°W., 77.3 ft. mkd: 1/4 S11 CS BT
Note - This corner lies approx. 325 ft. East of Rock Creek.

Steven Ness - For: Weyerhaeuser Co. - Oct. 1995 - M 123-3 A&B

Found - 2 1/2" GLO brass cap on 1" iron post.
38" D.Fir stump, N.19°35'E., 32.0' to center 30.65 to "W" nail. No face visible. Bark has fallen off. "W" in small low blaze. (N.19°E., 30.4)
continued next page

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 540600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 11

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

20" W.R. Cedar, S.37°37'E., 75.7. Face healed. (S. 37°E., 77.3)
25" G.Fir, N.32°25'W., 30.2. Face healed. (N.31½°W., 30.0)
15" W.R. Cedar stump. N.14°43'W., 42.7. Cruiser's mark "KM". (No Rec.)

BLM resurvey by A. Bert Skeesick, Cadastral Surveyor under Group #1979, surveyed May 2001/June 2002- (DCS0 rec. Vol. 54 Page(s) 20938)

The ¼ sec. cor. of secs. 2 & 11, monumented with an iron post, 1" dia., firmly set, projecting 6" above ground, with brass cap (properly) mkd. from which the remains of an original bearing tree

A decayed fir stump, 39" dia., bears N.18¾°E., 32.0 ft., with no marks visible. (Record, 30.4 ft.)

and bearing trees mkd. by V.R. Tracy, in 1966

A cedar, 22" dia., bears S.37½°E., 75.7 ft., with healed double blaze.

A fir, 28" dia., bears N.32½°W., 30.4 ft., with healed blaze.

and new bearing tree

A fir, 11" dia., bears S.68¾°W., 9.0 ft., mkd. ¼ S11 BT. Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center, unless otherwise described in the corner description