

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. Sec. 6 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John Littrell under Special Instructions dated June 13, 1867 (SEE DCSO records, GLO/BLM Michrofiche card 2 of 9 D41)

Set ¼ post on line between secs. 6 and 31, from which
A Red Fir 24" dia., bears S.5¼°E., 75 lks.
A Cedar 36" dia., bears N.42½°W., 40 lks.

Original - W.H. Byars, Under Contract #152 dated June 3, 1871 (DCSO records, Volume 7 Page 2943)

Set ¼ sec. post, from which
A Cedar 28" dia. bears S.50°E., 22 lks. dist.
A Fir 8" dia. bears N.50°W., 56 lks. dist.

GLO Dependent Resurvey, by Norman D.Price Under Special Instructions dated April 5, 1940 (DCSO records, Volume 27 Pages 11529-30)

Point for original ¼ sec. cor. of sec. 6 only, determined at the record bearing and distance from the old SE bearing tree. At point for corner, Set an iron post, 3 ft. long 1" dia., 28" in the ground, for ¼ sec. cor. of sec. 6 only, with brass cap marked:

¼ S6
1944 from which
A Fir stump 36" dia. bears S.5¼°E., 75 lks. dist., on which I uncovered the scribe marks S¼ beneath sufficient overgrowth to qualify the inscription for the date of the Littrell survey.
A Fir 24" dia. bears S.73°E., 25 lks. dist. mkd. ¼ S 6 B T. (New BT)
A Fir 8" dia. bears S.65°W., 40 lks. dist., mkd. ¼ S 6 B T. (New BT)

James W. Byron, Deputy Co. Surveyor - Ray Irving; John Fee January 6, 1955 - C.S. File 46/94

Found brass cap. Pipe bent. We broke pipe when we attempted to straighten it.
Set new brass cap mkd: ¼ S 6 T 25 S, R3W., Co. Sur. Office, 1954. From which I blaze and scribe:
10" R.Fir S.29°W., 27.0 ft. mkd. ¼ S6 T25S R3W CS BT.
(Cont Next Page)

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 140700

PRIMARY CORNER DESCRIPTION North ¼ cor. for Section 6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Note: I found 24" Fir, S.73°E., 16.5 ft. dist., partly grown over with some scribing visible. Also found original BT, now a 36" stump. Some scribe marks visible.

Found OK - BLM Resurvey by Wm. Glenn, Sept. 1958 (DCSO records, Volume 30 Pages 12592-93)

Found OK - Sept. 1966 - V. Tracy - C.S. File 54/27

Greg Lang - For: Seneca Jones Timber Co. - April 2001 - M 138-6 & C.S. File 65/37-5E

Found - DCSO 1954 Brass cap properly mkd.
Orig. Fir stump bears S.5¼°E., 48.3 ft. Sittrell
30" Fir bears S.72½°E., 16.0 ft. Price. Set spike in the base of the tree & placed new tag.
15" Fir bears S.27°W., 27.0 ft. Byron. Set spike in the base of the tree & placed new tag.

New BTs- 15" D.Fir bears N.35½°E., 31.7' scribed "¼ S6 only"
"BT" Set spike in the base of the tree & placed new tag.
10" D.Fir bears N.35½°W., 42.3' scribed "¼ S6 only"
"BT" Set spike in the base of the tree & placed new tag.

Note - On ridge & approx. 8' northerly of East-West fence.