

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Fd. Ok by DCSO July 1966 - C.S. 54/27-31

Doug. County Surveyors Office - V.R. Tracy and crew. Sept. 2, 1966 - C.S. File 54/27-66 (added to this rec. 10/30/2017)

Found - GLO brass cap (properly) mkd. in 1944 & stumps of BTs as follows:
14" Fir stump N.80°E., 31.7 ft. rotting badly - fragmentary scribe visible.
34" Fir stump S.77°W., 16.5 ft. "¼ S19 CS BT" scribe visible.
42" Fir stump N.26°E., 39.0 ft. "¼ S20 CS BT" scribe visible - beginning to rot.

New BTs- 4" D.Fir S.68°W., 11.1 ft. mkd: ¼ S19 CS BT.
4" D.Fir S.53½°E., 89.7 ft. mkd: ¼ S20 CS BT.

This cor. lies in N-S fence.

Doug. County Surveyors Office - R.W. Smith; S.J. Flause
March 28, 1989 - C.S. File 62/61-3

Found - 2½" 1944 GLO brass cap on a 27" long 1" I.P. out of ground bearing S.20°E., 22.5 ft. from a cor. position determined by bearing trees. GLO brass cap's stamping of section numbers is wrong. (reversed)
14" now 21" dia. 2½ ft. high rotted D.Fir stump, no scribing found, bears N.80°E., 31.7 ft. per 1944 resurvey.
30" now 30" dia., 6 ft. high D.Fir stump scribing visible on a previously opened blaze "¼ S19 BT" bears S.77°W., 16.5 ft., per 1944 resurvey.
42" now 36" dia., 2½ ft. high rotted D.Fir stump, with scribing visible "¼" bears N.26°E., 39.0'
4" now 15" dia. D.Fir with a fully healed double blaze bears S.68°W., 11.1 ft.
4" now 14" dia. D.Fir with a fully healed double blaze bears S.55½°E., 89.7 ft. (Rec. S.53½°E., 89.7 ft.) (Per 1966 visit)

Set - A corner position was determined from bearing trees A 2 3/8" dia. DCSO brass cap on a 1 3/8" O.D. by 32" long iron pipe is set and protrudes 7" above ground. Cap mkd. "Douglas County Surveyors T25S ¼ S19|S20 R3W 1989 Office". 1944 GLO BC/IP is set along north edge of new DCSO BC/IP and protrudes 3" above ground.

New BT - 11" dia. D.Fir double blazed and scribed "¼ S20 CS BT" bears N.59°E., 7.0 ft. continued next pg

