

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 200600

PRIMARY CORNER DESCRIPTION Sec Cor for 5, 6, 7 and 8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Pages 3724-25)

-----  
Set Cedar post 4" sq., 4 ft. long, 24" in the ground for sec. cor. to secs. 5, 6, 7 and 8, mkd. T25S S5 on NE., R3W S8 on SE., S7 on SW., and S6 on NW. faces, with 5 notches on E. edges, from which

- A Dogwood 6" dia., bears N.30°E., 40 lks. dist., mkd. T25S R3W S5 BT.
- A Fir 20" dia., bears S.41°E., 13 lks. dist., mkd. T25S R3W S8 BT.
- A Fir 18" dia., bears S.74°W., 15 lks. dist., mkd. T25S R3W S7 BT.
- A Fir 18" dia., bears N.26°W., 16 lks. dist., mkd. T25S R3W S6 BT.

GL0 Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Page 11601)

-----  
Point for original cor. of secs. 5, 6, 7, and 8, determined by reference to the record measurements from the old SE., SW., and NW. bearing trees.

At point for corner, set an iron post, 3 ft. long, 2" dia., 28" in the ground for cor., with brass cap mkd. T25S R3W

S6	S5
S7	S8
1944	

from which

- A Fir 40" dia., bears S.40°E., 13 lks. dist., with blaze healed. I re-blaze and re-mark this old bearing tree T25S R3W S8 BT.
- A Fir 18" dia., bears S.73½°W., 15 lks. dist., with blaze healed. (Old BT)
- A Fir 18" dia., bears N.18°W., 16 lks. dist., with partial scribe marks visible on portion of old blaze which has been previously uncovered. (Old BT)
- A Fir 30" dia., bears N.2 3/4°E., 74 lks. dist., mkd. T25S R3W S5 BT. (New BT)

Doug. County Surveyors Office - Vernon Tracy; Jack Heritage August 1966 - C.S. File 54/27-46

-----  
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. 5, 6, 7 and 8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Found - GLO brass cap mkd. 1944 with steel fence post alongside.  
Orig. 18" now 20" Fir S.73½°W., 9.9 ft., shows old scar. Do not open. (Rescribe "T25S R3W S7 CS BT".  
All other BTs now stumps.  
New BTs - 16" D.Fir S.59°W., 49.3 ft. mkd. T25S R3W S7 CS BT.  
18" D.Fir S.84°E., 55.3 ft. mkd. T25S R3W S8 CS BT.  
No other trees available.  
This corner lies on steep SE slope, cut off in Sec. 8.

Found OK by D. Edwards, Jan. 2001 - M136-33

Greg Lang - For: Seneca Jones Timber Co. - April 2001 - M 138-6 & C.S. File 65/37-5G  
-----  
Found - 1944 BLM brass cap properly mkd.  
30½" Fir bears S.84¼°E., 54.9 ft. Tracy. Set spike in the base of the tree & placed new tag.  
32" Fir bears S.72½°W., 10.7 ft. Wheeler. Set spike in the base of the tree & placed new tag.  
26" Fir bears S.57½°W., 49.0 ft. Tracy. Set spike in the base of the tree & placed new tag.  
New BTs - 9½" Fir bears N.65½°E., 32.6 ft. scribed "T25S R3W S5" "BT" Set spike in the base of the tree & placed new tag.  
8½" Fir bears N.59°W. 27.7 ft. scribed "T25S R3W S6" "BT" Set spike in the base of the tree & placed new tag.  
Set Alum. post at corner.  
Note - Corner is on steep SE Slope approx. 200 ft. easterly of ridge road.

Douglas Co. Surveyors Office - Crew: Stephen Flaue & Jeff Lorsung- 1/5/2022 (Filed 4/12/2022) - C.S. File 67/52-3  
-----  
Found - BLM brass cap projecting 6"  
29"x6' Fir, broken & burnt stump, S.84½°E., 54.5 (rec. 54.9) to 4" mag nail, side center.  
32"x5' saw burnt Fir stump S.57½°W., 49.0 ft. blaze burnt out.  
Burnt rotted roothole N.65½°E., 32.6 ft., evidence gone.  
10" burnt, dead, Fir snag N.59°W., 27.7 ft, fully healed blaze.  
Alum post along side cor.  
3 steel post N-E-S  
continued next page

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 200600

PRIMARY CORNER DESCRIPTION Cor Secs 5, 6, 7, & 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Note - Unrecorded  $\frac{5}{8}$ " I.Rod w/post alongside N.4°W. 54.3 ft  
Corner is on steep SE slope approx. 200' easterly of  
ridge road.  
Area burnt 9/2020  
Compass decl.  $14\frac{1}{2}$ °E.  
Lat: 43°25'20.84" N Long: 123°05'16.09" W