

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3704)

Set Hemlock post, 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on W. face, from which
A Fir 36" dia., bears N.65°E., 38 lks. dist.,
mkd. 1/4 S BT.
A Fir 60" dia., bears N.70°W., 17 lks. dist.,
mkd. 1/4 S BT.

GL0 Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Page 11578)

Point for original 1/4 sec.cor. determined by reference to the record measurements from both original bearing trees. At point for corner, set an iron post, 3 ft. long, 1" dia., 28" in the ground, for 1/4 sec. cor. with brass cap mkd.

1/4
S29|S28
1943 from which
A Fir 48" dia., bears S.71½°E., 38 lks. dist., mkd.
on bark 1/4 S BT. (Old BT)
A Fir 60" dia., bears N.54°W., 17 lks. dist., mkd.
on bark 1/4 S BT. (Old BT)
A Fir 22" dia., bears S.84½°E., 45 lks. dist., mkd.
1/4 S 28 BT. (New BT)
A Fir 32" dia., bears S.5°W., 63 lks. dist. mkd.
1/4 S 29 BT. (New BT)

Doug. County Surveyors Office - Vernon Tracy; Jack Heritage July 1966 - C.S. File 54/27-27

Found - 1943 GL0 brass cap mkd.
Orig. 1883 48" now 50" stump, S.71½°E., 25.1 ft. shows old bark scribe "1/4 S BT".
Orig. 60" Fir turned out and badly broken up, N.54°W., 11.2 ft., fragmentary bark scribe found.
22" now 24" Fir stump S.84½°E., 29.7 ft., shows scribe on unhealed blaze.
32" Fir, now stump S.5°W., 41.6 ft., no scribe fd.
New BTs - 24" D.Fir S.30°W., 63.3 ft. mkd. 1/4 S29 CS BT.
26" D.Fir N.38½°W., 84.7 ft. mkd. 1/4 S29 CS BT.
Corn. lies on N-S cutting line, cut off to East.

(Cont. Next Page)

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Doug. County Surveyors Office - Ed Monrean, Deputy - T. Plouff; S. Means; S. Flause; K. Mosley - May 7, 1980 - C.S. File 61/6-39

Found - 1943 GLO brass cap on 1" I.P. protruding 0.5 ft. from ground with cap properly mkd. Cap was found bent and loosely set.
Orig. 1883 48" D.Fir now a 50" stump, bears S.71½°E., 25.8 ft. face. (Orig. rec. N.65°E., 25.1 ft., 1943 GLO rec. S.71½°E., 25.1 ft.) 27.0 ft. to center of tree. We tagged with DCSO BT tag
Orig. 60" Fir turned out and badly broken up, N.54°W., 11.2 ft. (as per 1966 rec. and orig. rec. N.70°W., 11.2 ft.) No scribing found. We tagged tree with DCSO BT tag.
22" now 24" stump, S.84½°E., 29.7 ft., shows scribing "¼ S28 BT" on unhealed single blaze. We tagged with DCSO BT tags.
32" Fir now 50" stump bearing S.3½°W., 41.6 ft. (Rec. S.5°W., per 1966. No scribing found but low cut, portion of lower blaze appears to remain. We tag tree.
20" D.Fir (Rec. 24") bearing S.31°W., 63.3 ft. (Rec. S.30°W.) mkd. "¼ S29 CS BT" partially healed double blaze, barked and capped. We tagged with DCSO tag.
26" D.Fir bearing N.38½°W., 84.1 ft. mkd. "¼ S29 CS BT" on single blazed and uprooted away from hole.
Set - Because GLO cap bent, we reference out, RESET & stamp "Reset 1980" on existing cap. Cap protrudes 0.2 ft. from ground and is firmly set.
New - Set a 5/8" I.R. with alum. cap stamped "B0" on a 44" Fir stump bearing S.83½°E., 44.4 ft.
Scribed an 18" I.Cedar bearing S.1°W., 78.4 ft. Tree has a double blaze scribed "¼ S29 CS BT."
We tag new B.0. stump and new tree with DCSO BT tags
Corner is now on the N-S edge of a reproduction unit.

Ron Quimby - For: Roseburg Resources - March 2015 - M166-32

Found - 1943 GLO brass cap
36" tall, 24" stump S.84°E., 29.7' partially visible scribe.
5/8" iron rod w/aluminum cap stamped "B0" in 44" Fir stump S.83°E., 44.4'
72" tall, 50" fir stump S.71°E., 27.0' healed scar
continued next page

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

30" cedar S.1°W., 78.4' healed scar.
50" fir stump S.3°W., 41.6' rotten – no visible scar
60" tall, 20" fir stump w/metal cap S.31°W., 63.3'
partially healed scar

Douglas Co. Surveyors Office - Crew: Jeff Lorsung- 12/27/2023
- C.S. File 67/57-33

Found - 1943 GLO brass cap (properly mkd)
5/8" I.Rod with aluminum cap stamped B0 in 44" Fir
stump S.83°E., 44.4 ft. rod bent, dist to base.
50"x72" tall fir stump S.71°E. 27.0 ft. healed scar.
30" Cedar S.1°W., 78.4 ft. healed scar.
Steel post 1 ft. north.
All remaining BTs tagged, spike, all but the IR
stump.

Note - Area burnt 9/2020
Compass decl. 14½°E.
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 194017.802 E 233981.490