

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 340200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Dependent resurvey by A. Bert Skeesick & Kenneth W. Saveland, Cadastral Surveyors and Robert H. Browning, Survey Tech, under Group No. 2212 surveyed July/Oct. 2008 - (DCSO records Vol. 57 Page(s) 22440-1)

The ¼ sec. cor. of secs. 28 and 33, perpetuated by the Douglas County Surveyor's Office in 1966, monumented with an iron post, 1" dia., firmly set, projecting 10" above a collar of stone, with brass cap (properly) mkd.

from which the remains of an original bearing tree
A sawed, decayed fir stump, 49" dia., bears N.61°E., 4.0 ft., with no marks visible.

and the remains of a bearing tree mkd. by Price
A sawed fir stump, 29" dia., bears S.23½°E., 31.0 ft., with a healed double blaze.

and bearing trees mkd. by the Douglas County Surveyor's Office

A cedar, 25" dia., bears S.76½°E., 34.7 ft., with a healed blaze.

A fir, 18" dia., bears N.7½°W., 4.9 ft., with a healed blaze.

Corner is located on a W. slope.

Ron Quimby - For: Roseburg Resources - March 2015 - M166-32

Found - 1943 GLO brass cap
49" sawed fir stump N.61°E., 4.0' no visible scar
26" cedar S.76°E., 34.7' healed scar
72" tall, 29" sawed fir stump S.23°E., 31.0' healed scar.
20" fir N.7°W., 4.9' healed scar.