

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 & 4

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - GLO survey by Laban H. Wheeler, under Contract #467 dated April 7, 1883 (DCSO records, Vol. 9 Page 3701)

-----  
Set Yew post, 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on W. face, from which  
A Fir 6 dia. bears N.21°E., 13 lks. dist. mkd. 1/4 S BT  
A Fir 8" dia. bears N.73°W., 72 lks. dist. mkd 1/4 S BT

A. Boyer, Deputy Co. Surveyor - Wit: Ted Shellabager and Joe Murphy - April, 1940 - Vol. 4 Page 80; C.S. File 35/38

-----  
Set a Cedar post, 6" x 6" from which  
A Fir 15" bears S.73°E., 15.3 ft.  
A Fir 8" bears N.50°W., 25.0 ft.

GLO Dependent Resurvey by Norman D. Price under Special Instructions dated April 5, 1940 Survey, 1943 (DCSO records, Volume 27 Page 11575)

-----  
At proportional measurement, set an iron post, 3 ft. long 1" dia. 28" in the ground for 1/4 sec. cor., with brass cap mkd.  
1/4  
S4|S3  
1943 from which  
A Fir 12" dia. bears N.3°E., 91. lks. mkd. 1/4 S 3 BT.  
A Fir 10" dia. bears N.23°W., 129 lks. marked 1/4 S 4 BT.

Doug. Co. Surveyors Office - Vernon Tracy; Jack Heritage Sept. 1966 - C.S. File 54/27-76

-----  
Found - No trace of GLO brass cap set in 1944 resurvey. 10" now 16" Fir N.23°W., 85.0 ft., found reverse scribe previously removed from this BT., now rehealed, shows very good scar. NE BT, now stump, shows extreme bottom of scar. No scribe.  
Set brass cap at cor. mkd: County Surveyor's T 25 S R 3 W Office, 1966 1/4 S4|S3  
New BTs - 16" D.Fir N.86°E., 35.2 ft. mkd: 1/4 S3 CS BT.  
16" D.Fir N.28°W., 30.3 ft. mkd: 1/4 S 4 CS BT.

Found and used, Bureau of Land Management Dependent Resurvey by Rogers, Bedell and Peterson - Group #1386 - Survey June 1987-Sept. 1988 - (DCSO records, Volume 48 Page 18481)

Cont.

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 & 4

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 6/9/2022 (Filed 8/11/2022) - C.S. File 67/54-4

-----  
Found - DCS0 brass cap (properly mkd) proj. 12"  
Burnt-sawn 27"x2' D.Fir stump N.23°W., 84.2 ft.  
(Rec. 85.0 ft) Blaze face inside stump. 1940 BLM  
Burnt-dead 32" D.Fir S.89°E., 32.0 ft. (Rec. N.86°E.  
35.2 ft.) possible blaze add 3½" PK nail right  
side center. DCS0 1966  
Burnt-sawn 30"x1½' D.Fir stump N.30½°W. 30.6 ft.  
(rec N.28°W. 30.3 ft) blaze face visible inside  
stump add 3½" PK nail top center. DCS0 1966  
New - 5/8"x30" iron rod with yellow plastic cap proj. 4"  
S.22°E., 77.0 ft. in south shoulder of gravel rd.  
5/8"x30" iron rod with yellow plastic cap proj. 4"  
S.31°W., 70.7 ft. in south shoulder of gravel rd.  
Note - Corner is north of grave road.  
Area burnt 9/2020  
Compass decl. 14½°E.  
See sketch in file.  
Lat: 43°25'42.29"N Long: 123°02'53.07"W