

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3694)

-----  
Set post (Hemlock) 3 ft. long 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on the N. face, from which  
A Cedar 36" dia., bears N.35°W., 17 lks. mkd. 1/4 S BT.  
A Hemlock 12" dia., bears S.30°E., 14 lks. mkd. 1/4 S BT.

GLO Dependent Resurvey by Norman D. Price, Under Special Instructions April, 5, 1940. (DCSO records, Vol. 27 Pg 11567)

-----  
The original 1/4 sec. cor., the badly decayed point of a wooden stake on which only ax marks were found. At point for corner, set an iron post, 3 ft. long 1" dia., 28" in the ground with decayed remains of wooden stake deposited at the base for 1/4 sec. cor. with brass cap mkd. 1/4  $\frac{S22}{S27}$

1943 from which  
A Red Cedar 36" dia., bears N.42°W., 19 lks. with blaze healed, I re-blaze & re-mark this old BT 1/4 S 22 BT.  
A Fir 42" dia., bears S.20°E., 16 lks. mkd. on bark 1/4 S BT. I re-blaze and re-mark this old bearing tree 1/4 S27 BT.

Doug. County Surveyors Office - Vernon Tracy; Jack Heritage July 1966 - C.S. File 54/27-30

-----  
Found - 1943 GLO brass cap with steel fence post alongside. Orig. 1883 BTs remarked in 1943, as follows:  
36" now 42" Red Cedar N.42°W., 12.5 ft. mkd. 1/4 S22 BT, showing on partially healed blaze. Alive.  
42" now 48" Fir S.20°E., 10.6 ft. alive with 50" log lying against healed blaze. Due to size, we mark new BTs.

New BTs - 9" hemlock N.80°W., 32.2 ft. mkd. 1/4 S22 CS BT.  
9" Hemlock S.50°E., 26.2 ft. mkd. 1/4 S27 CS BT.

This cor. lies on E-W cutting line, cut off to North several years ago.

Doug. County Surveyors Office - Stephen Flause, Randall Smith October 1, 1986 - C.S. File 62/37-4

-----  
Found - GLO 2 1/2" bronze disk on a 1" dia., I.P. firmly set & protruding 8" from ground, properly mkd. dated 1943. Monument is in a rough 2 ft. dia. mound of stone. Monument is not disturbed to look for remains of wooden stake. continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 27

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Orig. BT, a Cedar, 36" dia., now a fallen and decayed 36" dia. Cedar bears N.42°W., 12.5 ft. (As per rec. 1943 resurvey and 1966 renewal - Orig. rec. N.35°W., 11.2 ft.) Evidence of rotted reblazed face found - no scribing found. No evidence of original Hemlock found.  
1943 resurvey 42" dia. Fir, now 54" dia. 1½ ft. tall Fir stump with no blaze or scribe marks found bears S.20°E., 10.6 ft. (as per record)  
1966 9" Hemlock now a 10" DBH 7 ft. tall Hemlock stump tipped out to north with a partially healed blaze with the scribing ¼ S22 CS BT visible bears N.80°W., 32.2 ft. at root crown.  
1966 9" Hemlock now a 10" dia., 3½ ft. tall Hemlock stump with a partially healed blaze with the scribing ¼ S27 CS BT visible bears S.50°E., 26.2 ft. (as per rec)  
Set - Monument position accepted as being that which was established in the 1943 resurvey from evidence of the original wooden post.  
New BTs- 6" DBH Hemlock scribed ¼ S22 CS BT on a double blaze bears N.13°E., 24.3 ft.  
14" DBH Hemlock scribed ¼ S22 CS BT on a double blaze bears N.63°W., 46.5 ft. dist.  
Monument is at north edge of recent clear-cut and at south boundary of well established reproduction unit. Monument is approx. 500 ft. north of BLM road No. 25-3-27.

Carl Sweeden - April 19, 2004 - C.S. File 65/49-27  
-----  
CONDITION REPORT ONLY  
Found - 1943 2½" BC up 0.80' in mound of stone, good cond.  
36" Cedar BT, down, N.42°W., 12.5' to root hole.  
42" D.Fir, stump, S.20°E., 10.6', no scribe vis.  
10" Hemlock BT, N.80°W., 32.2', tipped over, tag.  
10" Hemlock BT stump, S.50°E., 26.2', 5.0' tall scribe visible, tag.  
6" now 12" Hemlock, N.13°E., 24.3', dbl blaze, tag  
14" now 21" Hemlock, N.63°W., dbl blaze, tag.  
Note - Located at bottom of draw approx. 200' west of convergence of 2 small drainages.

continued next page

2

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 27

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM Dependent resurvey by A. Bert Skeesick & Kenneth W. Saveland, Cadastral Surveyors and Robert H. Browning, Survey Tech, under Group No. 2212 surveyed July/Oct. 2008 - (DCSO records Vol. 57 Page(s) 22439-40)

-----

The 1/4 sec. cor. of secs. 22 and 27, perpetuated by the Douglas County Surveyor's Office in 1966 and 1986, monumented with an iron post, 1" dia., firmly set, projecting 6" above ground, with brass cap (properly) mkd.

from which the remains of the original bearing trees

A sawed fir stump, 47" dia., bears S.20°E., 10.6 ft., with no marks visible.

A roothole bears N.42°W., 12.5 ft., alongside of which is the fallen cedar trunk, 38" dia., with no marks visible and the remains of a bearing tree mkd. by the Douglas County Surveyor's Office in 1966

A hemlock stump, size indeterminate, bears S.49¼°E., 26.2 ft., with scribe marks 1/4 S visible on an open blaze. and bearing trees mkd. by the Douglas County Surveyor's Office in 1986

A hemlock, 13" dia., bears N.13¾°E., 24.2 ft., with a healed double blaze.

A hemlock, 22" dia., bears N.62¾°W., 45.5 ft., with a healed double blaze.

and bearing tree mkd. by person(s) unknown

A hemlock, 11" dia., bears N.46¾°E., 8.9 ft., with a healed double blaze.

and a new bearing tree

A fir, 10" dia., bears S.42¾° E., 10.9 ft., mkd. ¼ S27 BT