

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3686)

Set Cedar post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 10, 11, 14 and 15, mkd. T25S S11 on NE., R3W S14 on SE., S15 on SW., and S10 on NW. faces, with 4 notches on S. and 2 notches on E. edges, from which
A Fir 40" dia., bears N.19°E., 10 lks., mkd. T25S R3W S11 BT.
A Cedar 18" dia., bears S.25°E., 30 lks., mkd. T25S R3W S14 BT.
A Fir 6" dia., bears S.41°W., 8 lks. mkd T25S R3W S15 BT
A Hemlock 8" dia., bears N.69°W., 9 lks., mkd. T25S R3W S10 BT.

GL0 Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Page 11559)

Point for orig. cor. of secs. 10, 11, 14 and 15, determined by reference to the record measurements from the old NE and NW bearing trees. At point for corner, set an iron post, 3 ft. long 2" dia., 28" in the ground, for cor. with brass cap mkd.

T25S R3W
S10|S11

S15|S14

1943

from which

The shattered remains of a Fir stump, 48" dia., bears N.88°E., 10 lks., on which ax marks were found. (Old BT)
A Hemlock 10" dia., bears N.16½°W., 9 lks., mkd. T25S R3W S10 BT. (Old BT)
A Fir 40" dia., bears N.51¾°E., 107 lks., mkd. T25S R3W S11 BT. (New BT)
A Yew, 8" dia., bears S.31¾°E., 46 lks., mkd. T25S R3W S14 BT. (New BT)
A Cedar 30" dia., bears S.58°W., 50 lks., mkd. T25S R3W S15 BT. (New BT)
A Hemlock 12" dia., bears N.6¾°W., 44 lks., mkd. T25S R3W S10 BT. (New BT)

Doug. County Surveyors Office - Vernon Tracy; Joe Brady; Jack Heritage - July/Aug. 1966 - C.S. File 54/27-49

Found - GL0 brass cap mkd. 1943, with steel fence post alongside.
continued next page

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

All BTs in very poor condition or gone completely.
Find scribe on 1943 resurvey BT to NE.
New BTs- 5" D.Fir N.13°E., 10.6 ft. mkd. S11 CS BT.
4" D.Fir N.42°W., 12.6 ft. mkd. S10 CS BT.
7" D.Fir S.14°W., 16.4 ft. mkd. T25S R3W S15 CSBT.
No other trees available.
This cor. lies on very steep west slope approx. 300 ft. East
of branch of S.Fork of Hinkle Creek in greasewood brush.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff
Lorsung- 10/17/2022 - C.S. File 67/54-27

Found - 2½" G:0 brass cap on 1½" I.D. Iron pipe,
straightened to plumb position, up 11"
Burned-rotted 18"x2' D.Fir stump, N.13°E., 10.6 ft.
1960
Burnt-sawn 22"x1 ft D.Fir stump N.44°W., 13.1 ft.
(rec. N.42°W., 12.6 ft.) new bearing & dist. to
3½" mag nail, top center. 1960
New - Burned-sawn 30"x3 ft. D.Fir stump N.22°E., 38.0 ft.,
3½" mag nail top center.
Burned-sawn 28"x3½ ft. D.Fir stump S.23½°E., 26.0
ft., 3½" mag nail top center.
Steel fence post 1 ft. south.
Note - Area burnt 9/2020
Compass decl. 14½°E.
ORCS Co-ordinate reference system south zone
Cottage Grove-Canyonville
N 209974.491
E 245461.055