

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3688)

Set Cedar post 3" sq., 3 ft. long, 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on W. face, from which
A Fir 30" dia., bears N.10°E., 5 lks. dist., mkd. 1/4 S BT.
A Hemlock 18" dia., bears N.19°W., 17 lks. dist., mkd. 1/4 S BT.

GLO Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Pages 11560-61)

The original 1/4 sec. cor., the badly decayed remains of a fir stake, 3 ft. long, 3" sq. on which only ax marks remain. At point for corner, Set an iron post, 3 ft. long 1" dia., 28" in the ground, with remains of fir stake deposited at the base for 1/4 sec. cor., with brass cap mkd.

1/4
S10|S11
1943 from which
A Fir 60" dia., bears S.48°W., 8 lks. dist., mkd. on bark 1/4 S BT. I reblaze and remark this old bearing tree, 1/4 S11 BT.
A Hemlock 30" bears N.37°W., 20 lks. dist., with no marks remaining on face of old blaze which has been mutilated about 20 years ago. (Old BT)
A Fir 42" dia., bears S.35°W., 52 lks. dist., mkd. 1/4 S10 BT. (New BT)

Doug. County Surveyors Office - Vernon Tracy; Joe Brady; Jack Heritage - Aug. 1966 - C.S. File 54/27-72

Found - GLO brass cap mkd. 1943, with steel fence post set alongside.
Orig. 60" Fir stump S.48°E., 5.3 ft. (recorded as S.48°W.), shows "BT" scribe on burned face.
Orig. 30" Hemlock stump N.37°W., 13.2 ft., burned, no scribe found.
42" now 43" Fir S.35°W., 34.3 ft., now badly burned stump, axe marks, no scribe.
New BTs - 5" D.Fir N.65°W., 41.6 ft. mkd. 1/4 S10 CS BT.
5" D.Fir N.36°E., 28.3 ft. mkd. 1/4 S11 CS BT.
Cor. lies on top of rounded spur, sloping south.

Cont.

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 and 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 12/12/2023 - C.S. File 67/57-27

Found - 2½" GLO brass cap (properly mkd) bent 1½ ft of plum, reference, remove, straighten & reset up 7"
Burned, rotted 40"x3 ft Fir stump S.48°E., 5.3 ft, face gone.
Burned away Fir stump, now a stub S.35°W., 34.3 ft.
Sawn, singed 30"x1½ ft D.Fir stump N.66°E., 41.4 ft. (rec. N.65°W., 41.6 ft) no blaze.
Sawn, singed 26"x1½ ft. D.Fir stump N.36°E., 27.3 ft (rec. 28.3 ft) face visible inside.
New - Sawn, singed 27"x3 ft. D.Fir stump S.89°E., 23.5 ft. 3½" mag nail top center.
Sawn, singed 8"x4½ ft. D.Fir stump S.1°W., 4.3 ft. 3½" mag nail top center.
Note - Area burned 9/2020
Compass decl. 14½°E.
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 212711.303 E 245448.717