

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 and 2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3690)

Set Cedar post, 3 ft. long 3" sq., 24" in the ground for 1/4 sec. cor., mkd. 1/4 S on W. face, from which
A Fir 30" dia. bears N.21°E., 17 lks. dist. mkd. 1/4 SBT.
A Fir 12" dia. bears S.73°W., 48 lks. dit. mkd. 1/4 SBT.

GL0 Dependent Resurvey by Norman D. Price, Under Special Instructions dated April 5, 1940 (DCSO records, Volume 27 Pages 11562-63)

Set by proportional measurement, an iron post 3 ft. long 1" dia., 28" in the ground, for 1/4 sec. cor., with brass cap mkd.
1/4
S3|S2
1944

from which
A Hemlock 12" dia. bears N.45°E., 25 lks. dist., mkd. 1/4 S2 BT.
A Hemlock 14" dia. bears N.78°W., 10 lks. dist., mkd. 1/4 S3 BT.

James W. Byron, Deputy Co. Surveyor - Milo Godfrey; Clete Putnam - March 24, 1960 - C.S. File 49/78

Found - Brass cap at corner and NW BT., now stump, shows good scribing "B". NE BT gone.
New BTs - 67" Fir stump bears N.74°W., 35.3 ft. scribed 1/4 S3 CS BT.
60" Fir stump bears S.68°E., 134.0 ft. scribed 1/4 S 2 CS BT.
(No trees near)

Doug. Co. Surveyors Office - Vernon Tracy; Jack Heritage August, 1966 - C.S. File 54/27-61

Found - GL0 brass cap 1944, and stumps of BTs as record by Byron, which are beginning to rot.
New BTs - 4" D.Fir S.9°W., 12.8 ft. mkd. 1/4 S3 CS BT.
4" Maple S.21°E., 17.0 ft. mkd. 1/4 S2 CS BT.
This cor. lies 20 ft. west of old logging road, course NW curving to SW.

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent Resurvey by Rogers, etal - Under Group #1386 dated June 1987 (DCSO records, Volume 48 Page 18480)

Found sec. cor. monumented with an iron post, 1" dia., firmly set, projecting 15" above ground with a 1944 brass cap. From which the remains of a bearing tree mkd. by Price:
The base of a tipped over Hemlock snag, 25" dia. bears N.78°W., 10 lks. dist., no marks visible.
And the bearing trees mkd. by Tracy in 1966:
A Maple 8" dia., bears S.21°E., 26 lks. dist., with healed blaze.
A Fir 15" dia. bears S.9°W., 19 lks. dist. with healed blaze.
and new bearing trees:
A Fir 8" dia. bears N.17°E., 15 lks. dist., mkd. ¼ S2 BT
A Fir 10" dia. bears S.33°W., 25 lks. dist., mkd. ¼ S3 BT
The corner is 50 lks. west of a graveled road, 20 lks. wide bears N.30°W., and S.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 6/7/2022 (Filed 8/11/2022) - C.S. File 67/54-3

Found - 2½" GL0 brass cap (properly mkd) on 1" iron pipe, proj 10"
Mostly burnt away tipped over 25" Hemlock snag N.78°E., 6.6 ft. Price BT
1' tall burnt Maple stub S.21°E., 17.2 ft. healed blaze. Tracy BT
17"x1½' burnt Fir stump S.9°W., 12.5 ft. healed blaze. Tracy BT
14"x6' burnt off D.Fir stump N.14°E., 10.1 ft. (Rec N.17°E., 9.9 ft) 3½" PK nail right center
12"x6½' ft burnt-sawn Fir stump S.30°W., 16.5 ft. (Rec. S33°W.) 3½" PK nail right center.
New - 13"x7' burnt-sawn D.Fir stump N.75°E., 14.8 ft. 3½" PK nail right center.
16"x1 ft. burned and sawn Fir stump S.55°E., 14.9 ft. 3½" PK nail top center
Note - Corner is approx. 35' west of gravel road ≈ 15' wide, bears N.30°W. and S.
Area burnt 9/2020
Compass decl. 14½°E.
See sketch in file.
Lat: 43°25'42.87"N Long: 123°01'40.46"W