

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 500700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3; 34 & 35 of T.24-3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W. H. Byars, Under Contract #152 dated June 3, 1871
(DCSO records, Volume 7 Page 2945)

Set post cor. to secs. 2, 3, 34 and 35, from which
A Fir 12" dia. bears N.60°E., 65 lks. dist.
A Fir 72" dia. bears S.30°E., 50 lks. dist.
A Fir 60" dia. bears S.10°W., 15 lks. dist.
A Fir 96" dia. bears N.70°W., 34 lks. dist.

GL0 Dependent Resurvey by Norman Price, Under Special Instructions
dated April 5, 1940 (DCSO records, Vol.27 PGs 11536-37)

By proportional measurement, set an iron post, 3 ft. long 2"
dia., 28" in the ground, for cor. of secs. 2, 3, 34 and 35,
with brass cap mkd.

T 24 S R 3 W

S 34 | S 35

S 3 | S 2

T25S

1944

from which

A Fir 60" dia., bears N.33¼°E., 79 lks. dist. mkd. T 24
S R 3 W S35 BT.

A Red Cedar 12" dia. bears S.29°E., 7 lks. dist., mkd.
T 25 S R 3 W S 2 BT.

A Fir 6" dia. bears S.48½°W., 61 lks. dist. mkd. T 25 S
R 3 W S 3 BT.

A Red Cedar 8" dia., bears N.51½°W., 57 lks. dist., mkd.
T 24 S R 3 W S34 BT.

Douglas County Surveyors Office - Ray Tracy; Jack Heritage
Sept. 1966 - C.S. File 54/27-131

Found - 1944 GL0 brass cap with steel fence post set along-
side and bent over. Reset fence post alongside
cap.

60" Fir stump N.33¼°E., 52.1 ft., shows "T24S R3W
S35 BT" scribe on unhealed blaze.

12" now 20" R.Cedar S.29°E., 4.6 ft. shows good
scar. Rescribe "T25S R3W S2 CS BT".

6" now 16" Fir S.48½°W., 40.3 ft. 48" log lying
against scar, only top of scar visible.

8" now 14" R.Cedar snag, N.51½°W., 37.6 ft., dead
& burned, no scribes.

New BTs - 6" D.Fir N.10°E., 23.9 ft. mkd. T24S R3W S35 CS BT.
17" R.Cedar N.69°W., 35.6 ft. mkd. T24S R3W S34
CSBT

Corner lies on moderate west slope approx. 120 ft. W. of top
of spur. _____ CONT

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 500700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3; 34 & 35 of T. 24-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Found OK, Burton Holt, Dec. 1981, M 90-16
Found and used, BLM Dependent Resurvey by Rogers, etal, Group #1386 - 1987-88 (DCSO records, Vol. 48 Pages 18476-77)

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 12/08/25 - C.S. File 67/61-49

Found - 2½" BLM brass cap proj 7".
Very burned and rotted 40" x5 ft. fir stump
N.33¼°E. 52.1 ft.
Burned, dead 30" R. Cedar S.29°E. 4.0 ft. (Rec 4.6 ft.) tree hollowed out.
Burned, rotted 23" x 7 ft. W. fir snag S.48½°W. 40.3 ft. top of scar visible.
Burned to stub. R. Cedar N.51½°W. 37.6 ft.
Burned, dead 28" D. Fir N.10°E. 24.3 ft. blaze not visible.
27" x 6 ft. R. cedar stump N.69°W. 35.6 ft. blaze not visible.

Fence post 1.0 ft. north.
Notes - Area burnt 9/2020
Mon near top of moderate S.W. slope. Clearcut N.W and S.E. Rest burnt trees.

Compass decl. 14¼°E.
OCS COORDINATE SYSTEM
COTTAGE GROVE-CANYONVILLE ZONE
N. 218706.541
E. 244919.842