

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3670)

Set cedar post, 3 ft. long, 3" sq., 24" in the ground for qr. sec. cor., mkd. $\frac{1}{4}$ S on W. face, from which

A Fir 10" dia., bears N.35°W., 9 lks. dist.,
mkd. $\frac{1}{4}$ S BT.

A Cedar 10" dia., bears N.31°E., 60 lks. dist.,
mkd. $\frac{1}{4}$ S BT.

GLO Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Page 11542)

Point for original $\frac{1}{4}$ sec. cor., determined by reference to the record measurements from both old bearing trees.

At point for corner, set an iron post, 3 ft. long, 1" dia., 28" in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.

$\frac{1}{4}$
S 26 | S 25
1943

from which

A Red Cedar 20" dia., bears N.37 $\frac{3}{4}$ °E., 60 lks. dist.,
on which I uncovered the scribe marks $\frac{1}{4}$ S BT
beneath 60 years overgrowth.

A Fir 30" dia., bears N.75°W., 9 lks., with blaze
healed. (Old BT)

A Fir 14" dia., bears N.42°E., 50 lks., mkd. $\frac{1}{4}$ S 25 BT.
(New BT)

BLM Dependent resurvey by A. Bert Skeesick & Kenneth W. Saveland, Cadastral Surveyors and Robert H. Browning, Survey Tech, under Group No. 2212 surveyed July/Oct. 2008 - (DCSO records Vol. 57 Page(s) 22419)

The $\frac{1}{4}$ sec. cor. of secs. 25 and 26, monumented with an iron post, 1" dia., firmly set, projecting 7" above ground, with brass cap (properly) mkd.

from which the remains of the original bearing trees

A partially uprooted cedar, 23" dia., bears N.37 $\frac{3}{4}$ °E.,
39.6 ft., with no scribe marks visible on an opened
blaze.

A sawed, decayed fir stump, 37" dia., bears N.75°W., 5.9
ft., with a healed blaze.

and the remains of a bearing tree mkd. by Price

continued next page

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 25 & 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A roothole bears N.42°E., 33.0 ft., alongside of which is a down, decayed, fir snag, 21" dia., with a healed blaze.
and new bearing trees
A fir, 8" dia., bears N.26¾°E., 7.6 ft., mkd. ¼ S25 BT.
A cedar, 8" dia., bears S.53¾°W., 24.6 ft., mkd. ¼ S26 BT.
Corner is located on a gradual E. slope, E., 180 ft. from a gravel road, 12 ft. wide, bears N.30°W. and S.30°E.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 5/3/2023 - C.S. File 67/56-11

Found - Monument destroyed by logging, rusted flange pieces found when digging new hole.
Sawn-burnt-rotted 32"x2 ft Fir stump, N.75°W., 5.9 ft., healed blaze, add 3½" mag nail top center.
Burned-dead, 9" D.Fir N.26¾°E., 7.6 ft. add 3½" mag. nail right side center, fully healed single blaze
Sawn-burnt 19"x1 ft cedar stump, S.53¾°W., 24.6 ft. partial scar, add 3½" mag nail top center.
Set - ¾" DCSO Alum. cap on 2"x30" alum. pipe, up 8", in rough stone mound, marked:
DOUGLAS COUNTY
SURVEYORS OFFICE
T25S R3W
¼ |
S26 | S25
2023
Note - Corner is located on a gradual E. slope, approx. 180 ft. E from 12 ft wide gravel road, bears N.30°W. and S.30°E.
Area burnt 9/2020
Compass decl. 14½°E.
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 192464.132
E 249265.710