

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 600540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 12

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3676)

-----  
Set Hemlock post, 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor., mkd. 1/4 S on W. face, on ridge, course E. and W. from which

A Hemlock 6" dia., bears E. 13 lks. dist. mkd. 1/4 S BT.

A Hemlock 12" dia., bears N.41°W., 14 lks. dist. mkd. 1/4 S BT.

GL0 Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Pages 11549-50)

-----  
Point for original 1/4 sec. cor. determined by reference to the record measurements from both old bearing trees. At point for corner, set an iron post, 3 ft. long, 1" dia., 28" in the ground, for 1/4 sec. cor., with brass cap mkd.

1/4  
S11|S12  
1943

from which

A Hemlock 7" dia., bears S.75 3/4°E., 13 lks. dist., mkd. 1/4 S BT. (Old BT)

A Hemlock 16" dia., bears N.36 1/2°W., 14 lks. dist. with blaze healed. (Old BT)

A Fir 40" dia., bears S.74 1/2°E., 45 lks. dist., mkd. 1/4 S12 BT. (New BT)

A Yew 8" dia., bears N.87°W., 47 lks. dist., mkd. 1/4 S11 BT. (New BT)

Doug. County Surveyors Office - Vernon Tracy; Joe Brady; Jack Heritage - July/Aug. 1966 - C.S. File 54/27-60

-----  
Found - GL0 brass cap mkd. "1/4 S11|S12 1943"., bent over & buried. We dig up & straighten BC & reset. All BTs destroyed by logging and fire. Scribe visible on 40" Fir stump, S.74 1/2°E., 29.7 ft.

New BTs - 5" D.Fir S.40°W., 19.4 ft. mkd. 1/4 S11 CS BT.  
24" Cedar stump S.67°E., 53.3 ft. mkd. 1/4 S12 CS BT. (7 ft. high)

Corner lies in old logged and burned area growing up to small fir & hemlock in heavy greasewood & willow brush.

continued next page

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 600540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 11 & 12

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 10/18/2022 - C.S. File 67/54-25

-----  
Found - 2½" GLO brass cap on 1" IP. Pipe bent badly.  
Replaced with new  
Burned-broken 30"xx4½ ft. Fir stump S.74½°E., 29.7 ft. 1940

Burned-sawn 38"x1 ft D.Fir stump S.40°W., 19.2 ft (rec. 19.4 ft) add 3½" mag nail top center.

Set - 3¼" alum cap on 2¼" I.D. alum pipe set at referenced position of old corner. MKD:

DOUGLAS COUNTY SURVEYORS OFFICE  
T25S R3W  
¼ S11|S12  
2022

New - 5/8"x30" iron rod with DCS0 Yellow plastic cap N.9°E., 48.0 ft. up 4"

5/8"x30" iron rod with DCS0 Yellow plastic cap N.39°E., 58.4 ft. up 4"

Steel fence post set 1 ft. South

Note - Area burnt 9/2020  
Compass decl. 14½°E.

ORCS Co-ordinate reference system south zone  
Cottage Grove-Canyonville  
N 210320.845  
E 249378.517