

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1, 2, 11 and 12

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_


Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3677)

-----  
 Set Cedar post, 4 ft. long, 4" sq., 24" in the ground for cor., mkd. T25S S1 on NE., R3W S12 on SE., S11 on SW., and S1 on NW., faces with 5 notches on S. and 1 notch on E. edges, from which

- A Fir 24" dia., bears N.35°E., 25 lks. dist. mkd. T25S R3W S1 BT.
- A Fir 48" dia., bears N.60°W., 13 lks. dist., mkd. T25S R3W S2 BT.
- A Hemlock 6" dia., bears S.75°W., 16 lks. dist., mkd. T25S R3W S11 BT.
- A Fir 10" dia., bears S.31°E., 54 lks. dist., mkd. T25S R3W S12 BT.

-----  
 GLO Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Page 11550)

-----  
 Point for original cor. of secs. 1, 2, 11 and 12, determined by reference to the record measurements from the old NE. and NW. bearing trees. At point for corner, set an iron post, 3 ft. long, 2" dia., 28" in the ground, for cor., with brass cap mkd.



- A stump hole, bears N.30°E., 25 lks. dist. (The old BT which stood in this position has slid down the mountain and is practically demolished)
- A stump hole, bears N.60°W., 13 lks. dist. (The old BT which stood in this position has slid down the mountain about 2.50 chains. The old surface scar and ax marks are visible but inaccessible on the under side of this uprooted fir tree which is 58" dia.)
- A Hemlock 30" dia., bears N.30 3/4°E., 88 lks. dist., mkd. T25S R3W S1 BT. (New BT)
- A Yew 9" dia., bears S.29°E., 46 lks. dist., mkd. T25S R3W S12 BT. (New BT)
- A Fir 28" dia., bears S.53 1/2°W., 43 lks. dist., mkd. T25S R3W S11 BT. (New BT)
- A Yew 12" dia., bears N.8 1/2°W., 33 lks. dist., mkd. T25S R3W S2 BT. (New BT)

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1, 2, 11 and 12

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Doug. County Surveyors Office - Vernon Tracy; Jack Heritage  
Aug. 1966 - C.S. File 54/27-40  
-----  
Found - GLO brass cap 1943, & stumps of 1943 BTs. All are  
cut too low or scribe burned off.  
New BTs - 6" Maple N.60°E., 44.4 ft. mkd. S1 CS BT.  
14" Hemlock N.32½°W., 126.6 ft. mkd. T25S R3W S2 CSBT  
Remark stump of 1943 BT, 15" Yew stump N.8½°W., 21.8  
ft. "T25S R3W S2 CS BT".  
No other trees available.  
Corner lies on steep west slope approx. 100 ft. W. of top of  
mountain.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff  
Lorsung- 11/2/2022 - C.S. File 67/54-47  
-----  
Found - 2½" brass cap on 1½" I.D. Iron pipe (properly mkd)  
up 14"  
Burnt, sawn 26"x5½ ft hemlock stump, N.34½°W.,  
(Rec N.32½°W.) 126.6 ft. Deep scar, face burnt  
New - 14"x3 ft Fir stump N.78°E., 15.0 ft. 3½" P.K. Nail  
top center.  
20"x2 ft. Fir stump S.63°E., 23.3 ft. 3½" P.K. Nail  
top center.  
13"x1 ft. Fir stump S.69°W., 8.9 ft. 3½" P.K. Nail  
top center.  
13"x1 ft. Fir stump N.12°W., 15.0 ft. 3½" P.K. Nail  
top center.  
Metal T. Post 1 ft. south.  
Note - Area burnt 9/2020  
Compass decl. 14½°E.  
O CRS Coordinate system  
Cottage Grove - Canyonville Zone  
N. 213209.049  
E. 249411.351