

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 24 and 25

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3671)

Set Cedar post 3 ft. long 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on N. face, from which
A Fir 8" dia., bears N.10°W., 16 lks., mkd. 1/4 S BT.
A Fir 12" dia., bears S.16°E., 22 lks., mkd. 1/4 S BT.

GL0 Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Pages 11543-44)

Proportional Measurement. Set an iron post, 3 ft. long 1" dia., 28" in the ground, for 1/4 sec. cor. with brass cap mkd
 $\frac{1}{4} \frac{S24}{S25}$
1943 from which

A Fir 56" dia., bears N.84½°W., 70 lks., mkd. 1/4 S24 BT.
A Red Cedar 20" dia. bears S.5°W., 22 lks. mkd. 1/4 S25 BT.

FD. Ok by Weyco. 1959 - C.S. File 53/113-6
Found OK, Nick Juliano, Dec. 1976, C.S. 58/130

BLM Dependent resurvey by A. Bert Skeesick & Kenneth W. Saveland, Cadastral Surveyors and Robert H. Browning, Survey Tech, under Group No. 2212 surveyed July/Oct. 2008 - (DCSO records Vol. 57 Page(s) 22421-2)

The 1/4 sec. cor. of secs. 24 and 25, perpetuated by McChesney, in 1959, monumented with an iron post, 1" dia., firmly set, projecting 8" above a collar of stone, with brass cap (properly) mkd.

from which bearing trees mkd. by Price
A cedar, 28" dia., bears S.5°W., 14.5 ft., with a healed blaze.

A sawed, decayed fir stump, 55" dia., bears N.84½°W., 46.2 ft., with a healed blaze.
and bearing trees mkd. by McChesney

A sawed cedar stump, 23" dia., bears N.52°E., 7.0 ft., with no marks visible on a partially healed blaze.
and a new bearing tree

A fir, 6" dia., bears N.25¾°W., 9.1 ft., mkd. 1/4 S24 BT.
Corner is located on a broken, NE. slope.

continued next page

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 24 & 25

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 6/22/2023 - C.S. File 67/56-41

Found - 2½" GLO brass cap on bent iron pipe referenced out, straightened, reset in proper location, up 10", rough stone around base.
36" burnt, dead, cedar S.8°W., 14.2 ft. (rec. S.5°W., 14.5 ft.) healed blaze, add 3½" mag nail right side center.
45"x4 ft. sawn, burnt, rotted fir stump N.84½°W., 46.7 ft. (rec. 46.2 ft) add 3½" mag nail right side center.
22"x5 ft. tall burned cedar stub N.52°E., 6.4 ft. (rec. 7.0 ft) add 3½" mag nail right side center.
9"x6" tall burnt, sawn fir stump N.28°W., 9.4 ft. (rec. N.25¾°W., 9.1 ft.) low blaze evidence add 3½" mag nail top center.

Note - Corner is approx 230 ft east of gravel logging road.
Area burnt 9/2020
Compass decl. 14½°E.
Corner on south edge of large clear cut on east-west cutting line, large second growth to south.

Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 196406.074 E 252394.947