

PRIMARY CORNER DESCRIPTION W. ¼ Cor. Sec. 7 only, T 25-2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 Dependent Resurvey by Norman D. Price, Under Special Instructions dated April 5, 1940 (DCSO records, Volume 27 Page 11517)

Mid-point on the W. bdy. of Sec. 7. Set an iron post 3 ft. long, 1" dia., 28" in the ground, for ¼ sec. cor. of sec. 7 only, with brass cap mkd. ¼ S7

1943 from which
A Fir 36" dia., bears S.57½°E., 57 lks., mkd. ¼ S7 BT.
A Fir 30" dia., bears S.81½°E., 50 lks., mkd. ¼ S7 BT.

Douglas Co. Surveyors Office - Vernon Tracy; Mike Stone; Jack Heritage - February 1966 - C.S. File 54/27-165

Found - 1943 GL0 brass cap under 36" log.
36" now 38" Fir, 4 ft. high stump, S.57½°E., 37.6 ft., face pitched over & nearly healed, no scribe visible.
30" now 32" Fir stump 3 ft. high, S.81½°E., 33.0 ft. healed blaze.
New BT - 30" Hemlock N.18°E., 19.4 ft. mkd. ¼ S7 CS BT.
(bearing approx. from top of log over brass cap.)
No trees to SE due to logging.
Corner lies in NW cor. of cut unit.

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor Under Group No. 2317, Surveyed June 2010/June 2011 - DCSO records Vol. 57 Page(s) 22790

The ¼ sec. cor. of sec. 7 only, on the W. bdy. of the Tp., perpetuated by the Douglas County Surveyors Office in 1966, monumented with an iron post, 1¼" dia., firmly set, projecting 7" above the ground, with brass cap (properly) mkd from which the remains of bearing trees mkd. by Price
A sawed, decayed fir stump, 40" dia., bears S.89½°E., 33.0 ft., with a healed blaze. (Record, S.81½°E.)
A sawed, decayed fir stump, 35" dia., bears S.67°E., 37.6 ft., with scribe marks S7 B visible on a partially healed blaze. (Record, S.57½°E.)
and a BT mkd. by the Douglas County Surveyor's Office
A hemlock, 38" dia., bears N.19½°E., 19.4 ft., with a healed double blaze.
and a new bearing tree
A fir, 6" dia., bears S.36°E., 19.0 ft., mkd. ¼ S7 BT.

continued next page

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 700533

PRIMARY CORNER DESCRIPTION W. ¼ Cor. Sec. 7 only; T25-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 7/17/2024 - C.S. File 67/58-37

Found - 2½" GLO brass cap (properly mkd) proj 6" add rough mound of stone around pipe.
Burnt, sawn rotted 32"x3½" ft Fir stump S.89½°E., 33.0 ft. healed blaze.
Burnt, sawn rotted 28"x4 ft. Fir stump S.67°E., 36.9 ft. (rec. 37.6 ft) blaze gone.
Burned, dead 39" Hemlock N.19½°E., 19.8 ft. (rec. 19.4 ft) healed double blaze, add 3½" mag nail right side center.
Burned, dead 5" Fir S.36°E., 18.9 ft. (rec. 19.0 ft) burned out double blaze, add 3½" mag nail right side center.
Alum post 1 ft. South.
New - Burned, dead 8" Hemlock N.53°E., 6.2 ft., 3½" mag nail right side center.
Note - Mon. on moderate East slope, burned old growth east, clear cut to west.
Gravel road approx 200 ft. west.
Area burnt 9/2020
Compass decl. 14¼°E.
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 210078.135 E 255345.983