

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 037030

PRIMARY CORNER DESCRIPTION Int. NW Cor. Iles DLC #37

Alias 046020 Description SE Cor. Hoskins DLC #46  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Dennis Hathorn, Contract dated Sept. 1856 (DCSO DLC records Page 177

-----  
Set stone post 12" long 10 wide 4 thick, from which  
A W.Oak 20" dia. bears S.70°E., 36 lks.  
A W.Oak 12" dia. bears N.2°W., 98 lks.

Ben B. Irving - 1929 - Vol. 5 Page 61 & C.S. File 37/13 - added 9/12/2018

-----  
Fair Oaks Cemetery plat showing that the SE cor of the Wm. Hoskins DLC 46 bears South 20.0 and E 231.0 from the sandstone 8"x8"x20" Initial Point of the Cemetery

Doug. Co. Surveyors Office - Sept. 17, 1956 - C.S. File 47/133 and C.S. File 37/13

-----  
Corner renewed at old fence post. N.W. BT found shows old blaze but not cut out. Ben B. Irving used old fence post for corner on Fair Oaks Cemetery job.  
Set brass cap at cor. mkd: S.E. Corner D.L.C. 46, T 25 S,  
R 4 W County Surveyor's Office, 1956  
32" B.Oak bears N.76°45'W., 46.5 ft. scribed S.E. corner Cl. 46 CS BT.  
34" W.Oak bears N.5°15'E., 65.0 ft. scribed S.E. corner Cl. 46 CS BT.

Doug. Co. Surveyors Office - Vernon Tracy; Mike Darby; Jack Barnett - January, 1965 - C.S. File 53/47-35

-----  
Found - Brass cap and one BT as recorded:  
34" W.Oak N.5¼°E., 65.0 ft. shows good upper and lower scars.  
New BT - 11" D.Fir N.82°E., 159.7 ft. mkd: SE DLC 46 CS BT.  
Brass cap lays on E. edge of driveway to Fair Oaks Church, flush with ground. SE cor. of Church bears N.42½°W., 66.2 ft

Doug. Co. Surveyors Office - Vernon Tracy; M. Darby; Jack Barnett - Sept. 19, 1968 - C.S. File 53/47-8

-----  
Found - DCSO brass cap flush with surface of ground marked "C.S. Office, 1956 S.E. Cor. Cl. 46".  
11" now 13" D.Fir alive, N.82°E., 159.7 ft. scribe visible on nearly healed blaze.  
New BT - 16" D.Fir N.5°W., 88.6 ft. mkd: "SE DLC 46 CS BT".  
SE Cor. of Fair Oaks Church bears N.38½°W., 66.2 ft. (Not N.42½°W.)

Cont.

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 037030

PRIMARY CORNER DESCRIPTION Int. NW Cor. Iles DIC #37

Alias 046020 Description SE Cor. Hoskins DIC #46  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Fd. OK, D. Bentz - November, 1987 - M 105-17  
Fd. OK, R. Dolan - Sept. 1992 - M 116-9.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -  
Stephen J. Flause - 1/28/2002 - C.S. File 66/32-12  
-----  
Found - 1956 DCSO brass cap/iron pipe, 4" below ground,  
leans 0.5 ft. south of plumb. We re-plumb BC/IP.  
No BTs found.  
SE corner of Church bears N.41°W., 66.7 ft. (1965  
rec. N.42½°W., 66.2 ft.) (1968 rec. N.38½°W.,  
66.2 ft.)  
A check was made to the 1979 DCSO state plane coord.  
tie. Back sight Plat B, set up on Fair Oaks,  
angle turned RT was observed as 259°43'46" 417.66  
ft. (Rec. per C.S. 60/30 259°46'32", 417.61) I  
attribute the small error to the plumbness of the  
BC/IP.  
1929 ½" Iron pipe in cemetery bears N.81¼°W., 240.9  
ft. (C.S. 37/13 rec. N.82¼°W., 242.7 ft.)  
1992 5/8" iron rod bears N.82¼°W., 230.8 ft. (M116-9  
rec. N.84¼°W., 230.0 ft.) in E-W fence line  
1" O.D. iron pipe protrudes 8" out of ground bears  
N.1°E., 104.5 ft.  
SE corner of red brick chimney at rec. hall house  
#866, bears N.40½°E., 60.0 ft.  
Note - Dec. 17½°

Fd. BC 12/2023 - by D. Edwards M183-18