

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 038020

PRIMARY CORNER DESCRIPTION S.E. Cor. Stratton DLC #38

Alias 050010 Description N.E. Cor. Deardorff DLC #50
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO DLC survey by Addison Flint under Contract 28, dated April 1854, surveyed July 1854 - (DCSO DLC records pg 173)*

Southeast corner of Claim 38 in Section 18, A post, from which:

A B.Oak 10" dia. bears N.53°W., ~~106~~ *105 lks. dist.

A B.Oak 8" dia. bears S.15°W., 25 lks. dist.

*** Corrected per research 9/15/2015 DCSO**

GLO DLC survey by Dennis Hathorn, Contract dated Sept. 1856 - (DCSO DLC records Pg 180)*

Beginning at the NE cor. DLC 50 which is the SE cor. Claim No. 38 from which

An Oak 12" dia., bears S.25°W., 25 lks.

An Oak 12" dia., bears N.35°W., 102 lks.

*** Corrected/added per research 9/15/2015 DCSO**

Sidney Strong, Chief Engineer of the S L & Water Co. - 1911 - S L & Water Co. Plat K, Vol. 3 Page 36 - **added 9/15/2015**

Stone NE Cor. Cl. 50 T25S R4W

Arthur Boyer, Wit. W.S. Crear and Mr. Crowell - December 1941 C.S. File 35/61 & "Old Corner Renewal Book" Page 192 *

*** "Old Corner Renewal Book" Page 192 record**

(Renewed from orig. BT, N.53°~~E~~ *W., 106 lks. 10" B.O.)

Set sandstone rock, cross on top & marked new tree to replace one lost in NW quadrant.

Laurel 12" dia. N.5°W., 15 ft.

W.Oak 15" dia. S.37°W., 47 ft.

*** Per C.S. File 35/61**

SE Cor. 38 = SS rock "+" on top.

10 B.O. N.53°~~E~~ *W., 106 lks.

8" B.O. S.15°W., 25 lks. Dead find scribe marks.

Set sandstone rock, cross on top & marked new tree to replace one lost in NW quadrant.

Laurel 12" dia. N.5°W., 15 ft.

W.Oak 15" dia. S.37°W., 47 ft.

*** Corrected/added per research 9/15/2015 DCSO**

continued next page

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 038020

PRIMARY CORNER DESCRIPTION SE Cor. Stratton DLC 38

Alias 050010 Description NE Cor. Deardorff DLC 50
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Lloyd Smith - For: Oregon Dept. of Forestry - 3/1983 (added 9/15/2015) - M94-1

Found - Sandstone by A. Boyer, 1941, in fence corner.
12" laurel N.5°W., 15.0' (now rotten stub S.57°W.,
7.0' (out of place))
15" W.Oak S.37°W., 47.0' (now 18" in place)

Douglas Co. Surveyors Office - Randall Smith & Stephen Flause
- Aug. 6, 1997 - C.S. 64/75-33

Found - Sand stone monument that measures 3"x6"x6" above
ground firmly set with cross on top (1941)
No OBT's found
12" Laurel now root hole, bears N.5°W. 15 (agrees
with rec.) 1941.
15" W.Oak now 18" B.Oak, with a fully healed double
blaze we open and find partial scribing, bears
S.36°W., 45.9' (Rec. S.37°W., 47' dist. is a
slope measurement) 1941.
Set - Corner lies in fence line no BC/IP is set
New - 8" D.Fir double blazed and scribed "SE DLC 38 CS
BT", bears N.41°E., 41.7'.
16" B.Oak single blazed and scribed "NE DLC 50 CS
BT", bears S.48°E., 41.6'.
25" P.Pine double blazed and scribed "NE DLC 50 CS
BT", bears S.78°W., 47.1'.

Fd. stone by D. Edwards 8/2013 - M165-58
Fd. stone by D. Edwards 2/2014 - C.S. 65/81-5 (Added 9/15/2015)