

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

<p>Original - Dennis Hathorn, Contract dated Sept. 1856 ----- Set post N W Cor., from which     An Oak 12" dia. bears N.13°W., 384 lks.     An Oak 12" dia. bears N.2°W., 415 lks.</p>
<p>Edwin S. Woodford - (Map filed 1961) - M 22-18 ----- Set 1" x 36" with gear attached.</p>
<p>Doug. Co. Surveyors Office - Vernon Tracy; Mike Darby; Jack Barnett - Jan/Feb 1965 - C.S. File 53/47-39 ----- Found - 1" steel shaft with gear attached.         No trace of original BTs. New BTs - 21" D.Fir N.64°E., 4.2 ft. mkd: N. N.W. DLC 49 CS BT           10" D.Fir N.26°W., 17.3 ft. mkd: N. N.W. DLC 49 CSBT This cor. lies in E-W fence approx. 100 ft. East of fence cor.</p>
<p>Found OK, August, 1992 by Donald Peel - M 115 - 62</p>
<p>Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - May 6, 1996 - C.S. File 64/66-16 ----- Found - A 1" dia, by 32" long axle with 3" dia., gear, out of the ground. (1922)         21" now 28" dia., down, D.Fir, (appears that tree twisted as it went down, fully healed double blaze faces North) bears N.64°E., 4.2 ft. is per 1965 DCSO rec. We were unable to determine a position for this BT. (1965 DCSO)         10" now 14" dia., D.Fir, with fully healed double blaze, bears N.26°W., 17.3 ft. (Agrees with 1965 DCSO rec). (1965 DCSO)         No evidence OBTs found. Position of corner determined from DCSO 1965 North West BT. Set - 2 3/8" dia., brass cap on a 1 3/8" dia., by 32" long iron pipe, protrudes 10" above ground. Axle is set along south edge of BC/IP, protrudes 8" above ground. New BTs - 11" dia., D.Fir, double blazed and scribed "NNW DLC 49 CS BT", bears N.81½°W., 6.0 ft.           4" dia., D.Fir, double blazed &amp; scribed "X BT", bears S.29½°W., 20.9 ft.           7" dia., D.Fir, double blazed &amp; scribed "NNW DLC 49 CS BT", bears S.9°E., 30.6 ft.</p>
<p>1</p>