

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 260200

PRIMARY CORNER DESCRIPTION E 1/16 Cor. for Secs. 29 & 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Bureau of Land Management Dependent Resurvey - Zirpel, Corbin and Roseberry - Special Instructions dated July 8, 1957 and July 15, 1958 (DCSO records, Volume 29 page 12305)

Set an iron post, 28" long, 2½" dia., 26" in the ground, with brass cap marked:

S 29
E 1/16 S 32
1957 from which

A Fir 18" dia. bears N.54°E., 40½ lks. dist. marked
E 1/16 S29 BT.
A Fir 7" dia. bears S.30°45'E., 61 lks. dist. marked
E 1/16 S32 BT.

Douglas Co. Surveyors Office - V. Tracy; M. Darby; J. Barnett
Jan./Feb. 1965 - C.S. File 53/47-10

Found - 1957 BLM brass cap and one live BT:
7" now 10" Fir S.30 3/4°E., 40.3' blaze healed over.
Did not open.
18" Fir N.54°E., 26.7 ft. laying face up.
New BT - 5" D.Fir N.22°E., 19.7 ft. mkd: E 1/16 S29 CS BT.

Bureau of Land Management Dependent Resurvey - Jelley and Rogers, Group #1084. Survey, Jan-June 1982 (DCSO records, Volume 45 Page 17519)

Found - 1957 BLM brass cap.
A root hole bears N.54°E., 40½ lks. dist. with an uprooted Fir alongside, 22" dia. with fragmentary scribe marks visible on open blaze.
A Fir 10" dia. bears S.30 3/4°E., 58 lks. dist. with healed blaze. (Record, 61 lks.)
New BT - A Fir 9" dia. bears N.41°W., 153 lks. dist. marked
E 1/16 S 29 BT.