

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 35

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - W. H. Byars, Deputy Surveyor under Contract #152 dated June, 1871 - (DCSO records, Volume 9 Page 3765)

-----  
Set 1/4 sec. post, from which  
A Cedar 6" dia. bears N.6°W., 22 lks. dist.  
A Fir 5" dia. bears S.4°W., 14 lks. dist.

James W. Byron, Deputy Co. Surveyor - For: Wilbur Lbr. Co. November 1955 - C.S. File 47/44 and M 2-1

-----  
Corner set at midpoint and on true line between section cors.  
Set iron pipe with brass cap mkd: 1/4 S 26 Co. Sur Office 1955.  
S 35

Blazed & Scribed:  
10" Cedar N.33°47'E., 255.01 ft. mkd. 1/4 S 26 C.S. BT.  
10" Cedar S.25°31'30"E., 60.29 ft. mkd. 1/4 S 35 C.S. BT.

Bureau of Land Management Dependent Resurvey - Zirpel; Corbin and Roseberry - Special Instructions dated July 8, 1957 and July 15, 1958 - (DCSO records, Volume 29 Page 12279-80)

-----  
Found - 1955 County brass cap.  
A Cedar 10" dia. bears N.29°45'E., 386 lks. dist.  
mkd. 1/4 S26 CS BT on an unhealed blaze.  
A Cedar 10" dia. bears S.28 1/4°E., 93 lks. dist. mkd.  
1/4 S35 CS BT on an unhealed blaze.

At the corner point set an iron post 28" long 2 1/2" dia. 26" in the ground, with brass cap marked:

T25S R4W  
1/4 S 26  
S 35

1957 from which  
A Cedar 13" dia. bears N.39 1/2°E., 508 lks. mkd 1/4 S 26 BT.  
A Cedar 12" dia. bears S.10°E., 178 1/2 lks. mkd 1/4 S35 BT.  
Deposit county surveyor's corner alongside the iron post.

Vernon Tracy; M. Darby; J. Barnett - Doug. Co. Surveyors Off. Feb-March 1965 - C.S. File 53/47-65

-----  
Found - BLM and County brass caps.  
10" now 16" Cedar N.29 3/4°E., 254.8 ft. scribe vis. on partially grown over blaze. This tree recorded by Byron as N.33°47'E., 255.01 ft.  
13" now 16" Cedar N.39 1/2°E., 335.3 ft. "1/4 S26 BT" visible on partially grown over blaze.

Both BTs to south down and out of place.  
New BT - 9" Cedar S.50°E., 98.5 ft. mkd. 1/4 S35 CS BT.

Cont.

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas Co. Surveyors Office - Larry E. Monrean, Deputy; T.R. Plouff - November 16, 1981 - C.S. File 61/29-22

-----  
Found - BLM brass cap at the ¼ cor. location, properly stamped, approx. 2" above ground, along N'thly side of BC is a 1" I.P. with County brass cap, properly stamped, protruding 10" above ground.  
10" Cedar now 24" with well healed blaze bears N.31°E., 254.8 ft (Rec. per Byron, N.33°47'E., 255.01 ft. - per 1957 Resurvey, N.29°45'E., 254.8 ft.)  
13" Cedar now a 24" stump about 6 ft. high with well healed blaze bears N.40¾°E., 331.3 ft. (Rec. N.39½°E., 335.3 ft. (Byron))  
9" now 19" Cedar with well healed blaze bears S.48¾°E., 98.5 ft. (Record S.50°E.)  
No monument set, but we do remove the County Surveyor brass cap monument leaving the BLM cap at corner position as found.  
New BTs - 8" D.Fir double blazed & scribed "¼ S26 CSBT" bears N.49½°E., 13.1 ft.  
8" D.Fir single blazed & scribed "¼ S35 CS BT" bears West, 62.5 ft. This tree has logs lying around the base - blaze is centered approx. 2 ft above ground.  
New B0 - Set an angle iron fence post 2.0 ft. west of monument.

Ken Hoffine, Lone Rock Timber Co. - 1/19/2012 - CS 65/76-11

-----  
Condition Report only  
Found - 1957 BLM BC (properly mkd) 0.2 ft. above ground level, with angle iron fence post 2.0 ft. west of corner.  
25" D.Fir Bears S.88°W., 61.7 ft. (Rec. West 62.5 ft.) Healed Face and BT Tag  
14" D.Fir Bears N.48¾°E 13.2 ft. (Rec N.49½°E., 13.1 ft.) Healed Face and Tag  
35" Cedar Bears S.49½°E., 98.8 ft. (Rec. S.48¾°E., 98.5 Ft.) Healed Face and Tag  
Lone Rock ran a random traverse conventional survey from the S¼ easterly to the SESC, then northerly to the E1/4 corner of section 26, which we close with GPS. The purpose of survey is to blaze and paint true line between monuments for timber management purposes. We located the above monuments during the course of this survey.

cont.

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 35

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Dan Saily, Lone Rock Timber Co. - Crew: Trevor Clemo & Ignacio Roman - 2/2024 - C.S. File 65/113-33

-----  
Found - 1957 BLM brass cap and iron pipe.  
28" D.Fir with Douglas County tag and well healed face bears S.88°W., 61.8' rec. S.88°W. 61.75.  
14" D.Fir with Douglas County tag and well healed face bears N.48½°E., 13.7 rec. N.48¾°E. 13.2'.  
37" I.Cedar, missing tag. with a well healed face bears S.49½°E., 98.7' record S.49½°E., 98.8. We tag.  
Angle iron fence post fd per rec bears West 2.0.  
New - 15" D.Fir bears S.23½°W., 15.6' we tag & scribe ¼ S35 BT  
Note - FD 1957 BLM brass cap and iron pipe as per 1957-58 BLM record VOL. 29 PG 12279-80. The top of the monument is 0.25 ft above ground level. The monument lies on an east facing slope, approximately 100 ft east and 100 ft north of a small creek running SE. We ran a random closed loop traverse from the quarter corner of secs 26 & 35 to the corner of secs 26, 27, 34 & 35. BTs were measured with a TOPCON ES62 TOTAL STATION to an aluminum nail at side center for distance & at center face for bearings.  
Basis of bearing: 1957-58 BLM which is based on a solar observation.