

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 14

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

An Ash 10" dia. bears N.51°W., 14 lks. dist. marked $\frac{1}{4}$ S 11 BT.
A Fir 21" dia. bears S.29½°W., 110 lks. dist. marked $\frac{1}{4}$ S 14 BT.
Reset axle alongside the iron post.
Corner falls alongside corner of fences extending N. and E.

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 1/13/98 - C.S. File 64/79-3

Found - 3¼" dia., brass cap on a 2½" O.D. iron pipe protrudes 8" above ground (1957)
1" dia., axle protrudes 7" above ground is found along North edge of BC/IP.(1929)
21" now rotted to ground D.Fir, bears S.29½°W., 72.6 ft. (Agrees with rec.) 1957
10" now 13" dia., Ash with a partially healed single blaze scribing visible, " $\frac{1}{4}$ S11 BT" bears N.51°W., 9.2 ft. (agrees w/rec.) 1957
1929 SE BT now gone.
14" now 23" dia., W.Oak with a fully healed double blaze, bears N.38°W., 46.7 ft. (rec. N.42°W., 48.9 ft.) 1929
10" now rotted Ash stump, no marks visible bears N.42°W., 9.2 ft. (Agrees with rec.) OBT
New BTs- 26" dia., I.Cedar, double blazed and scribed " $\frac{1}{4}$ S11 CS BT" bears N.21°E., 101.1 ft.
11" dia., B.Oak, double blazed and scribed " $\frac{1}{4}$ S11 CS BT" bears N.76°E., 43.9 ft.
Corner lies at the intersection of fences running North-East 10 ft. South of an East-West drainage.

Found OK by N. Hibbs, Oct. 2002 - M141-15